

Curb Ramp Self Evaluation Results - Parks

OBJECTID	C1	C2	C3	C4	C5	C6	C7	C8	C9	C10	C11	Comment	x	y	ADA Compliant
255	Big Marine	Other	Yes	≤8.3%	≤2%	≥4ft	Yes	≤10%	Yes	Yes	Yes		-92.8731	45.20574	TRUE
256	Big Marine	Other	Yes	≤8.3%	≤2%	≥4ft	Yes	≤10%	Yes	Yes	Yes		-92.8724	45.20452	TRUE
265	Big Marine	Other	Yes	<5%	≤2%	≥4ft	No	≤10%	Yes	Yes	Yes		-92.8715	45.203	FALSE
266	Big Marine	Other	Yes	<5%	≤2%	≥4ft	No	≤10%	Yes	Yes	Yes		-92.8716	45.20303	FALSE
267	Big Marine	Other	Yes	<5%	≤2%	≥4ft	Yes	≤10%	Yes	Yes	N/A		-92.8723	45.20403	TRUE
270	Big Marine	Other	Yes	≤8.3%	≤2%	≥4ft	Yes	≤10%	Yes	Yes	Yes		-92.8724	45.2041	TRUE
272	Big Marine	Other	Yes	<5%	≤2%	≥4ft	No	≤10%	Yes	Yes	Yes		-92.8696	45.20342	FALSE
275	Big Marine	Other	Yes	≤8.3%	≤2%	≥4ft	No	≤10%	Yes	Yes	Yes		-92.8697	45.20392	FALSE
286	Big Marine	Other	Yes	<5%	≤2%	≥4ft	No	≤10%	Yes	Yes	Yes		-92.8811	45.20207	FALSE
287	Big Marine	Other	Yes	≤8.3%	≤2%	≥4ft	No	≤10%	Yes	Yes	Yes		-92.8809	45.20209	FALSE
289	Big Marine	Other	Yes	<5%	≤2%	≥4ft	No	≤10%	Yes	Yes	Yes		-92.8808	45.20202	FALSE
291	Big Marine	Other	Yes	<5%	≤2%	≥4ft	No	≤10%	No	Yes	Yes	Needs updating	-92.881	45.20223	FALSE
293	Big Marine	Other	Yes	<5%	≤2%	≥4ft	No	≤10%	Yes	Yes	Yes		-92.8809	45.20227	FALSE
295	Big Marine	Other	Yes	≤8.3%	>2%	≥4ft	Yes	≤10%	Yes	Yes	Yes		-92.8808	45.20237	FALSE
308	Big Marine	Other	Yes	≤8.3%	≤2%	≥4ft	No	≤10%	Yes	Yes	Yes		-92.8703	45.20401	FALSE
309	Big Marine	Other	N/A	<5%	≤2%	≥4ft	No	N/A	No	N/A	Yes		-92.8733	45.20571	FALSE
310	Big Marine	Other	N/A	<2%	≤2%	≥4ft	Yes	N/A	No	N/A	Yes		-92.8725	45.20344	FALSE
311	Big Marine	Other	N/A	<2%	>2%	≥4ft	Yes	N/A	No	N/A	Yes		-92.8726	45.20333	FALSE
312	Big Marine	Other	N/A	≤8.3%	≤2%	≥4ft	No	N/A	No	N/A	Yes		-92.8742	45.20291	FALSE
313	Big Marine	Other	N/A	<5%	≤2%	≥4ft	Yes	N/A	No	N/A	Yes		-92.8741	45.20284	FALSE
314	Big Marine	Other	N/A	<5%	>2%	≥4ft	No	N/A	No	N/A	Yes	Cross 2.3	-92.8797	45.20176	FALSE
315	Big Marine	Other	N/A	<2%	≤2%	≥4ft	Yes	N/A	No	N/A	Yes		-92.8797	45.20167	FALSE
321	Big Marine	Parallel	Yes	<5%	≤2%	≥4ft	No	≤10%	Yes	Yes	Yes		-92.8627	45.04011	FALSE
748	Big Marine	Directional	Yes	≤8.3%	≤2%	≥4ft	Yes	≤10%	Yes	No	Yes		-92.9746	44.9838	FALSE
415	Cottage Grove Ravine	Other	Yes	>8.3%	>2%	≥4ft	No	>10%	No	N/A	Yes		-92.9003	44.80643	FALSE
416	Cottage Grove Ravine	Other	No	<5%	>2%	<4ft	No	N/A	No	N/A	Yes		-92.9002	44.8065	FALSE
1298	Cottage Grove Ravine	Perpendicular	Yes	<5%	≤2%	≥4ft	Yes	≤10%	Yes	Yes	Yes		-92.9002	44.82602	TRUE
1299	Cottage Grove Ravine	Perpendicular	Yes	≤8.3%	≤2%	≥4ft	Yes	≤10%	Yes	Yes	Yes		-92.9004	44.826	TRUE
1300	Cottage Grove Ravine	Perpendicular	Yes	≤8.3%	≤2%	≥4ft	Yes	≤10%	Yes	Yes	Yes		-92.9005	44.8261	TRUE
1301	Cottage Grove Ravine	Directional	Yes	<2%	≤2%	≥4ft	Yes	≤10%	Yes	Yes	Yes		-92.9014	44.8261	TRUE
1302	Cottage Grove Ravine	Directional	Yes	<5%	≤2%	≥4ft	No	≤10%	Yes	Yes	Yes		-92.9017	44.82606	FALSE
429	Lake Elmo	Depressed Corner	Yes	<5%	≤2%	≥4ft	Yes	≤10%	No	N/A	Yes		-92.895	44.9945	FALSE
435	Lake Elmo	Other	N/A	<2%	≤2%	≥4ft	Yes	N/A	No	No	Yes		-92.8923	44.99014	FALSE
448	Lake Elmo	Other	N/A	<5%	≤2%	≥4ft	No	N/A	No	N/A	Yes		-92.8906	44.9871	FALSE
449	Lake Elmo	Other	N/A	<5%	≤2%	≥4ft	Yes	N/A	No	N/A	Yes		-92.8905	44.98711	FALSE
467	Lake Elmo	Parallel	Yes	>8.3%	≤2%	≥4ft	No	>10%	No	N/A	Yes		-92.8899	44.98298	FALSE
468	Lake Elmo	Parallel	Yes	<5%	≤2%	≥4ft	Yes	>10%	No	N/A	Yes		-92.8932	44.98468	FALSE
479	Lake Elmo	Other	N/A	<2%	≤2%	≥4ft	Yes	N/A	Yes	Yes	Yes		-92.9036	44.97599	TRUE
480	Lake Elmo	Depressed Corner	N/A	≤8.3%	≤2%	≥4ft	Yes	N/A	Yes	Yes	Yes		-92.9036	44.97604	TRUE
481	Lake Elmo	Depressed Corner	N/A	≤8.3%	≤2%	≥4ft	No	N/A	Yes	Yes	Yes		-92.9035	44.97592	FALSE
483	Lake Elmo	Depressed Corner	N/A	<2%	≤2%	≥4ft	Yes	N/A	Yes	Yes	Yes		-92.9033	44.97593	TRUE
486	Lake Elmo	Depressed Corner	N/A	<2%	>2%	≥4ft	No	N/A	Yes	Yes	Yes		-92.9025	44.97707	FALSE
487	Lake Elmo	Depressed Corner	N/A	<2%	≤2%	≥4ft	Yes	N/A	Yes	Yes	Yes		-92.9028	44.97694	TRUE
488	Lake Elmo	Directional	Yes	≤8.3%	≤2%	≥4ft	Yes	≤10%	Yes	Yes	Yes		-92.9023	44.97711	TRUE
489	Lake Elmo	Directional	Yes	<2%	≤2%	≥4ft	Yes	≤10%	Yes	Yes	Yes		-92.9024	44.97717	TRUE
492	Lake Elmo	Directional	Yes	<2%	≤2%	≥4ft	Yes	≤10%	Yes	Yes	Yes		-92.9026	44.97741	TRUE
493	Lake Elmo	Parallel	Yes	≤8.3%	≤2%	≥4ft	Yes	≤10%	Yes	Yes	Yes		-92.9027	44.9774	TRUE
499	Lake Elmo	Depressed Corner	Yes	<5%	≤2%	≥4ft	Yes	>10%	No	No	Yes		-92.9033	44.97054	FALSE
501	Lake Elmo	Other	Yes	≤8.3%	≤2%	≥4ft	Yes	>10%	No	N/A	Yes		-92.9033	44.97089	FALSE

Curb Ramp Self Evaluation Results - Parks

OBJECTID	C1	C2	C3	C4	C5	C6	C7	C8	C9	C10	C11	Comment	x	y	ADA Compliant
1347	Lake Elmo	Perpendicular	N/A	<2%	>2%	≥4ft	No	N/A	No	N/A	Yes		-92.9033	44.97146	FALSE
1348	Lake Elmo	Perpendicular	N/A	<5%	>2%	≥4ft	No	N/A	No	N/A	Yes		-92.9035	44.97154	FALSE
1349	Lake Elmo	Perpendicular	N/A	≤8.3%	≤2%	≥4ft	No	N/A	No	N/A	Yes		-92.9005	44.9816	FALSE
1350	Lake Elmo	Perpendicular	N/A	>8.3%	≤2%	≥4ft	No	N/A	No	N/A	Yes	Large crack	-92.9005	44.98151	FALSE
1351	Lake Elmo	Perpendicular	N/A	<5%	≤2%	≥4ft	Yes	N/A	No	N/A	Yes		-92.8984	44.98465	FALSE
1352	Lake Elmo	Perpendicular	N/A	>8.3%	≤2%	≥4ft	No	N/A	No	N/A	Yes		-92.8985	44.98474	FALSE
1353	Lake Elmo	Perpendicular	N/A	<5%	≤2%	≥4ft	Yes	N/A	No	N/A	Yes		-92.896	44.98401	FALSE
1354	Lake Elmo	Perpendicular	N/A	<5%	≤2%	≥4ft	Yes	N/A	No	N/A	Yes		-92.896	44.98394	FALSE
1355	Lake Elmo	Perpendicular	N/A	<5%	≤2%	≥4ft	No	N/A	No	N/A	Yes		-92.8964	44.984	FALSE
1356	Lake Elmo	Perpendicular	N/A	<2%	≤2%	≥4ft	No	N/A	No	N/A	Yes		-92.8964	44.98411	FALSE
1357	Lake Elmo	Perpendicular	Yes	>8.3%	≤2%	≥4ft	No	N/A	Yes	Yes	Yes	No landing gravel path. Large step	-92.89	44.98301	FALSE
1358	Lake Elmo	Perpendicular	Yes	>8.3%	≤2%	≥4ft	No	N/A	Yes	Yes	Yes	Gravel path for landing large step	-92.8905	44.98321	FALSE
1359	Lake Elmo	Perpendicular	Yes	>8.3%	≤2%	≥4ft	No	N/A	Yes	Yes	Yes	Large step	-92.8906	44.98327	FALSE
1381	Lake Elmo	Perpendicular	Yes	>8.3%	>2%	<4ft	Yes	>10%	No	N/A	Yes		-92.8934	44.98441	FALSE
1382	Lake Elmo	Perpendicular	N/A	<5%	>2%	≥4ft	No	N/A	No	N/A	Yes	Cross8.2	-92.8986	44.98778	FALSE
1383	Lake Elmo	Perpendicular	N/A	≤8.3%	>2%	≥4ft	No	N/A	No	N/A	Yes	Cross8	-92.8987	44.98766	FALSE
1384	Lake Elmo	Perpendicular	N/A	>8.3%	≤2%	≥4ft	No	N/A	No	N/A	Yes		-92.8978	44.98993	FALSE
1385	Lake Elmo	Perpendicular	N/A	>8.3%	≤2%	≥4ft	Yes	N/A	No	N/A	Yes		-92.8977	44.98996	FALSE
1386	Lake Elmo	Perpendicular	N/A	<5%	>2%	≥4ft	No	N/A	No	N/A	Yes		-92.8964	44.99027	FALSE
1387	Lake Elmo	Perpendicular	N/A	<5%	≤2%	≥4ft	Yes	N/A	No	N/A	Yes		-92.8966	44.99027	FALSE
1388	Lake Elmo	Perpendicular	N/A	<5%	>2%	≥4ft	Yes	N/A	No	N/A	Yes		-92.8911	44.98881	FALSE
1389	Lake Elmo	Perpendicular	N/A	<5%	≤2%	≥4ft	No	N/A	No	N/A	Yes		-92.891	44.98887	FALSE
1390	Lake Elmo	Perpendicular	N/A	<2%	≤2%	≥4ft	Yes	N/A	No	N/A	Yes		-92.8903	44.98891	FALSE
1391	Lake Elmo	Perpendicular	N/A	<2%	>2%	≥4ft	Yes	N/A	No	N/A	Yes		-92.8904	44.98898	FALSE
1392	Lake Elmo	Perpendicular	N/A	>8.3%	>2%	≥4ft	No	N/A	No	N/A	Yes		-92.8872	44.98745	FALSE
1393	Lake Elmo	Perpendicular	N/A	<5%	>2%	≥4ft	No	N/A	No	N/A	Yes	8.5cross	-92.8871	44.98724	FALSE
1394	Lake Elmo	Perpendicular	N/A	<5%	>2%	≥4ft	Yes	N/A	No	N/A	Yes		-92.8873	44.98741	FALSE
1395	Lake Elmo	Fan	N/A	<2%	≤2%	≥4ft	No	N/A	No	N/A	Yes		-92.8908	44.98723	FALSE
1396	Lake Elmo	Perpendicular	Yes	<5%	≤2%	≥4ft	Yes	>10%	No	N/A	Yes		-92.8909	44.9873	FALSE
1397	Lake Elmo	Perpendicular	Yes	<5%	>2%	≥4ft	Yes	N/A	No	N/A	Yes		-92.891	44.9874	FALSE
1398	Lake Elmo	Other	N/A	<5%	≤2%	≥4ft	No	N/A	No	N/A	Yes		-92.8909	44.9885	FALSE
1479	Pine Point	Other	N/A	>8.3%	≤2%	≥4ft	No	N/A	No	N/A	Yes		-92.8379	45.12064	FALSE
345	Point Douglas	Other	Yes	≤8.3%	≤2%	≥4ft	Yes	>10%	No	N/A	Yes		-92.8095	44.74935	FALSE
346	Point Douglas	Depressed Corner	Yes	≤8.3%	>2%	≥4ft	Yes	>10%	No	N/A	Yes		-92.8086	44.74901	FALSE
347	Point Douglas	Depressed Corner	Yes	<5%	≤2%	≥4ft	Yes	>10%	No	N/A	Yes	Gutter slope not compliment	-92.8113	44.74967	FALSE
1412	Square Lake	Perpendicular	N/A	<5%	≤2%	≥4ft	No	N/A	No	N/A	Yes		-92.7935	45.15452	FALSE
1413	Square Lake	Perpendicular	N/A	≤8.3%	≤2%	≥4ft	No	N/A	No	N/A	Yes		-92.7943	45.15471	FALSE
1415	Square Lake	Perpendicular	N/A	>8.3%	>2%	≥4ft	No	N/A	No	N/A	No	Cracks	-92.7945	45.15265	FALSE
1416	Square Lake	Perpendicular	N/A	<5%	>2%	≥4ft	No	N/A	No	N/A	No	Large bump at start	-92.7947	45.15255	FALSE
1480	Square Lake	Other	N/A	≤8.3%	>2%	≥4ft	No	N/A	No	N/A	No		-92.7963	45.15266	FALSE
362	St. Croix Bluffs	Depressed Corner	N/A	<2%	>2%	≥4ft	No	N/A	No	N/A	No		-92.796	44.80053	FALSE
392	St. Croix Bluffs	Depressed Corner	N/A	<2%	≤2%	≥4ft	Yes	N/A	No	N/A	Yes		-92.8013	44.80197	FALSE
396	St. Croix Bluffs	Depressed Corner	N/A	<5%	>2%	≥4ft	Yes	N/A	No	N/A	Yes		-92.8039	44.80157	FALSE
397	St. Croix Bluffs	Parallel	Yes	>8.3%	≤2%	<4ft	Yes	≤10%	No	N/A	Yes	Updates may be needed soon	-92.804	44.80142	FALSE
398	St. Croix Bluffs	Other	Yes	>8.3%	≤2%	≥4ft	Yes	>10%	No	N/A	Yes		-92.8039	44.80139	FALSE
1455	St. Croix Bluffs	Parallel	N/A	<5%	>2%	≥4ft	No	N/A	No	N/A	No		-92.796	44.80042	FALSE

Facility Entrance Self Evaluation - Parks

OBJECTID	E1	E2	E3	E4	E5	E6	E7	E8	E9	E10	E11	E12	E13	E14	E15	E16	Comment	x	y	ADA Compliant
21	Lake Elmo	Yes	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes		-92.89495396	44.99455872	FALSE	
23	Lake Elmo	Yes	N/A	N/A	N/A	No	Yes	Yes	No	Yes	N/A	Yes	Yes	Yes	Yes		-92.90225116	44.97739225	FALSE	
24	St. Croix Bluffs	Yes	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	N/A	N/A	N/A	-92.80407468	44.8013968	FALSE	
27	Lake Elmo	Yes	N/A	N/A	N/A	No	N/A	Yes	No	Yes	N/A	Yes	Yes	N/A	Yes	Yes	-92.9032222	44.9707249	FALSE	
29	Big Marine	Yes	N/A	N/A	N/A	No	Yes	Yes	Yes	Yes	N/A	Yes	Yes	N/A	N/A	N/A	-92.88103262	45.20216337	FALSE	

Parking Lot Self Evaluation Results - Parks

OBJECTID	P1	P2	P3	P4	P5	P6	P7	P8	P9	P10	P11	P12	P13	P14	P15	P16	Comment	x	y	Van accessible parking requirements	Meeting Van Requirements?	ADA Compliant
1	Pine Point	No	44	1	No	No	N/A	N/A	N/A	No	Yes	N/A	No	N/A	N/A	Yes		-92.83808517	45.12088851	1	yes	FALSE
7	Square Lake	No	84	1	No	Yes	N/A	N/A	N/A	Yes	Yes	N/A	Yes	N/A	N/A	N/A		-92.79395286	45.15484405	1	yes	FALSE
8	Square Lake	Yes	12	3	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	No	Yes	No	Yes	Not all spaces have signage	-92.79566983	45.15257585	1	yes	FALSE
9	Square Lake	No	110	2	No	No	N/A	N/A	N/A	No	N/A	No	N/A	N/A	N/A	Yes		-92.79409403	45.15286336	1	yes	FALSE
10	Big Marine	Yes	67	3	Yes	Yes	Yes	Yes	Yes	Yes	No	Yes	Yes	No	Yes	Yes	Closest to picnic area not close to play area	-92.87169661	45.20319533	1	yes	FALSE
11	Big Marine	Yes	67	4	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	No	Yes		-92.87258434	45.20436097	1	yes	FALSE
13	Big Marine	Yes	40	2	No	Yes			Yes	Yes	Yes	Yes	Yes	N/A	Yes			-92.87020413	45.20374416	1	yes	FALSE
14	Big Marine	No	20	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		-92.87390527	45.20594501	0	yes	FALSE
15	Point Douglas	No	158	4	Yes	Yes	Yes	No	Yes	Yes	Yes	Yes	Yes	Yes	No	Yes		-92.8096409	44.74925622	1	yes	FALSE
16	St. Croix Bluffs	Yes	93	3	Yes	Yes	Yes	No	Yes	Yes	No	Yes	Yes	Yes	No	Yes		-92.78748982	44.79933434	1	yes	FALSE
17	St. Croix Bluffs	No	38	1	No	No	N/A	N/A	N/A	No	No	No	Yes	Yes	N/A	Yes		-92.79327525	44.80079163	1	yes	FALSE
18	St. Croix Bluffs	Yes	35	2	Yes	Yes	Yes	Yes	Yes	Yes	No	Yes	Yes	Yes	No	Yes	Accessible route not in got condition	-92.79616937	44.80054728	1	yes	FALSE
19	St. Croix Bluffs	Yes	5	1	Yes	Yes	No	Yes	Yes	Yes	No	Yes	Yes	Yes	Yes	Yes		-92.7907617	44.80277147	1	yes	FALSE
20	Cottage Grove Ravine	Yes	51	2	Yes	N/A	Yes	Yes	Yes	Yes	No	Yes	Yes	Yes	No	Yes		-92.89990602	44.80641958	1	yes	FALSE
26	Lake Elmo	N/A	25	1	Yes	N/A	Yes	N/A	Yes	Yes	No	Yes	Yes	No	No	Yes		-92.89491415	44.99444	1	yes	FALSE
27	Lake Elmo	No	167	2	Yes	N/A	Yes	N/A	Yes	Yes	No	Yes	Yes	Yes	No	Yes		-92.89209606	44.98994029	1	yes	FALSE
28	Lake Elmo	Yes	131	3	Yes	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	No	Yes		-92.89063106	44.98734571	1	yes	FALSE
29	Lake Elmo	Yes	27	2	Yes	No	No	No	Yes	No	No	N/A	Yes	No	No	No		-92.88663014	44.9869353	1	yes	FALSE
30	Lake Elmo	Yes	20	2	Yes	No	No	No	Yes	No	No	Yes	Yes	Yes	N/A	Yes		-92.88961259	44.98122357	1	yes	FALSE
32	Lake Elmo	Yes	225	4	Yes	No	No	No	Yes	No	No	No	Yes	Yes	No	Yes	No aisles marked	-92.89018298	44.98278427	1	yes	FALSE
33	Lake Elmo	Yes	216	11	Yes	No	No	No	Yes	No	No	No	Yes	Yes	No	Yes	No aisles marked	-92.89373756	44.98468592	2	yes	FALSE
34	Lake Elmo	Yes	13	1	Yes	No	No	No	Yes	No	No	No	Yes	Yes	No	Yes	No aisles marked	-92.89659278	44.98114659	1	yes	FALSE
35	Lake Elmo	Yes	99	4	Yes	Yes	N/A	Yes	Yes	Yes	No	Yes	Yes	Yes	Yes	Yes		-92.90278743	44.97725709	1	yes	FALSE
39	Big Marine	Yes	5	1	Yes	N/A	N/A	Yes	Yes	Yes	No	Yes	Yes	Yes	No	Yes		-92.88121621	45.20207356	1	yes	FALSE
42	Lake Elmo	No	35	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		-92.90000093	44.98794438	0	yes	FALSE
43	Lake Elmo	no	16	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		-92.89735575	44.9905467	0	yes	FALSE
44	Cottage Grove Ravine	No	18	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		-92.90044164	44.80403016	0	yes	FALSE
45	St. Croix Bluffs	no	5	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		-92.79623174	44.7994358	0	yes	FALSE
46	St. Croix Bluffs	no	5	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		-92.79319109	44.80202913	0	yes	FALSE
47	Cottage Grove Ravine	No	40	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No marked. 40 spaces is best estimate	-92.90500319	44.80487759	0	yes	FALSE
48	Lake Elmo	No	4	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		-92.90306828	44.97086325	0	yes	FALSE
49	Lake Elmo	No	6	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		-92.89865451	44.98137966	0	yes	FALSE
50	Lake Elmo	No	2	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		-92.89793573	44.98136181	0	yes	FALSE
51	Lake Elmo	No	6	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		-92.89468819	44.98079344	0	yes	FALSE
60	St. Croix Bluffs	No	5	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		-92.79356503	44.79963035	0	yes	FALSE
61	St. Croix Bluffs	No	5	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		-92.79053992	44.80220762	0	yes	FALSE
62	St. Croix Bluffs	No	13	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		-92.78797874	44.80305583	0	yes	FALSE
63	St. Croix Bluffs	No	4	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		-92.78995412	44.80407766	0	yes	FALSE
65	Lake Elmo	Yes	108	4														-92.90431847	44.97543771	1	yes	TRUE
66	Lake Elmo	no	42	0														-92.90416214	44.98183414	0	yes	FALSE
67	Lake Elmo	No	10	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		-92.8969495	44.9855578	0	yes	FALSE
69	St. Croix Bluffs	Yes	2	1	No	N/A	N/A	N/A	N/A	Yes	No	Yes	Yes	Yes	N/A	Yes		-92.79256348	44.80022559	1	yes	FALSE

Sidewalk Self Evaluation Results - Parks

OBJECTID	S1	S2	S3	S4	S5	S6	S7	S8	Comment	x	y	ADA Compliant
177	Big Marine	Yes	Yes		N/A	≤5%	≤2%	No		-92.87208603	45.20395454	TRUE
178	Big Marine	N/A	Yes	N/A	N/A	≤5%	≤2%	No		-92.87250211	45.20341073	TRUE
187	Big Marine	Yes	Yes	N/A	N/A	≤5%	≤2%	No		-92.86956098	45.20349052	TRUE
188	Big Marine	Yes	Yes		N/A	≤5%	≤2%	No		-92.86957758	45.20372966	TRUE
225	Big Marine	Yes	Yes	N/A	N/A	≤5%	≤2%	No		-92.8713371	45.20308203	TRUE
226	Big Marine	Yes	Yes	N/A		≤5%	>2%	No		-92.87073336	45.20308928	FALSE
227	Big Marine	Yes	Yes		N/A	>5%	≤2%	No		-92.87070905	45.20320902	FALSE
228	Big Marine	Yes	Yes		N/A	≤5%	>2%	No		-92.87121708	45.20382903	FALSE
229	Big Marine	Yes	Yes		N/A	≤5%	≤2%	No		-92.87079262	45.20379386	TRUE
230	Big Marine	Yes	Yes		N/A	≤5%	>2%	No	2.2cross slope	-92.8705187	45.20405106	FALSE
231	Big Marine	Yes	Yes	N/A		≤5%	≤2%	No		-92.87008577	45.20405672	TRUE
232	Big Marine	Yes	Yes	N/A	N/A	>5%	>2%	No		-92.87153542	45.20400848	FALSE
233	Big Marine	Yes	Yes	N/A	N/A	>5%	>2%	No	2.4 cross slope	-92.87150307	45.20426509	FALSE
234	Big Marine	Yes	Yes	N/A	N/A	≤5%	>2%	No	3.8 cross slope	-92.87114415	45.20428194	FALSE
235	Big Marine	Yes	Yes	N/A	N/A	>5%	>2%	Yes	Run 5.1 cross 2.6 concrete cracking	-92.87216985	45.20472514	FALSE
236	Big Marine	Yes	Yes	N/A	N/A	>5%	≤2%	No		-92.87247671	45.20504951	FALSE
237	Big Marine	Yes	Yes	N/A	N/A	≤5%	≤2%	No		-92.87303037	45.20536981	TRUE
238	Big Marine	Yes	Yes	N/A	N/A	≤5%	≤2%	No		-92.8736407	45.2056849	TRUE
239	Big Marine	Yes	Yes	N/A	N/A	≤5%	>2%	No	Cross 2.4	-92.87236389	45.20468855	FALSE
240	Big Marine	Yes	Yes	N/A	N/A	>5%	>2%	No	Run 9 cross 3.4	-92.87224956	45.20408216	FALSE
241	Big Marine	Yes	Yes	N/A	N/A	>5%	≤2%	No	Run 8.2	-92.87189777	45.20379504	FALSE
242	Big Marine	Yes	Yes	N/A	N/A	>5%	≤2%	No	Run 8	-92.87172519	45.20357535	FALSE
243	Big Marine	Yes	Yes	N/A	N/A	≤5%	>2%	No	Cross 2.1	-92.87217932	45.20303782	FALSE
244	Big Marine	Yes	Yes	N/A	N/A	≤5%	≤2%	No		-92.87196692	45.20281557	TRUE
1013	Big Marine	Yes	Yes	N/A	N/A	≤5%	≤2%	No		-92.88146673	45.20252241	TRUE
1015	Big Marine	Yes	Yes	N/A	N/A	≤5%	≤2%	No		-92.88091824	45.20216333	TRUE
1019	Big Marine	Yes	Yes	N/A	N/A	≤5%	≤2%	No		-92.8725793	45.2028097	TRUE
1020	Big Marine	Yes	Yes	N/A	N/A	≤5%	≤2%	No		-92.87217496	45.20278141	TRUE
1021	Big Marine	Yes	Yes	N/A	N/A	≤5%	≤2%	No		-92.8717847	45.20282253	TRUE
1023	Big Marine	Yes	Yes	N/A	N/A	≤5%	>2%	No		-92.87151698	45.20326928	FALSE
330	Cottage Grove Ravine	Yes	Yes	N/A	N/A	>5%	>2%	No		-92.90043429	44.80638927	FALSE
331	Cottage Grove Ravine	Yes	Yes	N/A	N/A	≤5%	≤2%	No		-92.90101315	44.80621501	TRUE
935	Cottage Grove Ravine	Yes	Yes	N/A	N/A	≤5%	≤2%	No		-92.90263452	44.82609844	TRUE
936	Cottage Grove Ravine	Yes	Yes	N/A	N/A	≤5%	≤2%	No		-92.9009746	44.82609718	TRUE
937	Cottage Grove Ravine	Yes	Yes	N/A	N/A	≤5%	>2%	No		-92.90041042	44.82516978	FALSE
938	Cottage Grove Ravine	Yes	Yes	N/A	N/A	≤5%	>2%	No		-92.8993837	44.8237941	FALSE
939	Cottage Grove Ravine	Yes	Yes	N/A	N/A	≤5%	≤2%	No		-92.89943576	44.82294352	TRUE
940	Cottage Grove Ravine	Yes	Yes	N/A	N/A	≤5%	≤2%	No		-92.90137442	44.82201002	TRUE
941	Cottage Grove Ravine	Yes	Yes	N/A	N/A	≤5%	≤2%	No		-92.90271535	44.82108734	TRUE
942	Cottage Grove Ravine	Yes	Yes	N/A	N/A	≤5%	>2%	No		-92.90283621	44.81991357	FALSE
943	Cottage Grove Ravine	Yes	Yes	Yes	N/A	≤5%	>2%	No		-92.90022173	44.80654262	FALSE
944	Cottage Grove Ravine	Yes	Yes	N/A	N/A	≤5%	>2%	No		-92.90292238	44.82126363	FALSE
945	Cottage Grove Ravine	Yes	Yes	N/A	N/A	≤5%	≤2%	No		-92.90291903	44.82209364	TRUE
946	Cottage Grove Ravine	Yes	Yes	N/A	N/A	≤5%	>2%	No		-92.90293789	44.82290174	FALSE
947	Cottage Grove Ravine	Yes	Yes	N/A	N/A	≤5%	≤2%	No		-92.90270445	44.82361546	TRUE
948	Cottage Grove Ravine	Yes	Yes	N/A	N/A	>5%	≤2%	No		-92.90284367	44.82428379	FALSE
270	Lake Elmo	Yes	Yes	N/A	N/A	≤5%	>2%	No		-92.90328573	44.969756	FALSE
271	Lake Elmo	Yes	Yes	N/A	N/A	≤5%	>2%	No		-92.90329353	44.96870067	FALSE
272	Lake Elmo	Yes	Yes	N/A	N/A	≤5%	>2%	No		-92.90325623	44.96794387	FALSE

Sidewalk Self Evaluation Results - Parks

OBJECTID	S1	S2	S3	S4	S5	S6	S7	S8	Comment	x	y	ADA Compliant
273	Lake Elmo	Yes	Yes	N/A	N/A	≤5%	>2%	No		-92.90325087	44.96702459	FALSE
274	Lake Elmo	Yes	Yes	N/A	N/A	≤5%	>2%	No		-92.90326294	44.96600765	FALSE
275	Lake Elmo	Yes	Yes	N/A	N/A	≤5%	>2%	No		-92.90326872	44.96508275	FALSE
276	Lake Elmo	Yes	Yes	N/A	N/A	≤5%	>2%	No		-92.90312866	44.96424351	FALSE
349	Lake Elmo	Yes	Yes	Yes	N/A	≤5%	>2%	N/A		-92.8922373	44.9907147	FALSE
359	Lake Elmo	Yes	Yes	N/A	No	≤5%	>2%	Yes	Hole forming in path	-92.88929483	44.98136804	FALSE
367	Lake Elmo	Yes	Yes	Yes	N/A	>5%	>2%	Yes	Becoming degraded	-92.89645524	44.98122366	FALSE
380	Lake Elmo	Yes	Yes	N/A	N/A	≤5%	≤2%	No		-92.9023592	44.97747284	TRUE
381	Lake Elmo	Yes	Yes	N/A	N/A	≤5%	≤2%	No		-92.9021753	44.97723429	TRUE
745	Lake Elmo	Yes	Yes	N/A	N/A	≤5%	>2%	No		-92.8926787	44.98447576	FALSE
746	Lake Elmo	Yes	No	No	N/A	≤5%	≤2%	No	To narrow	-92.89267332	44.98424529	FALSE
747	Lake Elmo	Yes	No	No	N/A	≤5%	≤2%	N/A		-92.89156138	44.98475479	FALSE
748	Lake Elmo	Yes	Yes	N/A	N/A	>5%	>2%	Yes	Slight lip	-92.89260769	44.99043172	FALSE
749	Lake Elmo	Yes	Yes	N/A	N/A	≤5%	≤2%	No		-92.89074565	44.98674226	TRUE
750	Lake Elmo	Yes	Yes	N/A	N/A	≤5%	≤2%	No		-92.89080818	44.98698311	TRUE
1040	Lake Elmo	Yes	Yes	N/A	N/A	≤5%	≤2%	No		-92.90222391	44.97681126	TRUE
137	Pine Point	Yes	Yes	N/A	Yes	>5%	≤2%	No	Concrete slabs separating creating gap	-92.83794226	45.12056798	FALSE
138	Pine Point	Yes	Yes	N/A	No	>5%	≤2%	No		-92.83789731	45.12060239	FALSE
263	Point Douglas	Yes	Yes	N/A	N/A	≤5%	≤2%	Yes		-92.80937573	44.74930909	FALSE
264	Point Douglas	Yes	Yes	N/A	N/A	≤5%	≤2%	No		-92.80831626	44.74901133	TRUE
265	Point Douglas	Yes	Yes	N/A	N/A	≤5%	≤2%	No		-92.80725712	44.74871855	TRUE
266	Point Douglas	Yes	Yes	No	N/A	≤5%	>2%	No		-92.80703567	44.74868452	FALSE
267	Point Douglas	Yes	Yes	No	N/A	≤5%	≤2%	No		-92.80609346	44.74865367	FALSE
268	Point Douglas	Yes	Yes	N/A	N/A	≤5%	>2%	No		-92.81044744	44.74956902	FALSE
269	Point Douglas	Yes	Yes	N/A	N/A	≤5%	>2%	Yes	Sand washed away ground. Huge crack forming in path	-92.81199331	44.74977609	FALSE
988	Square Lake	Yes	Yes	N/A	N/A	≤5%	≤2%	No		-92.79510948	45.1537845	TRUE
989	Square Lake	Yes	Yes	No	N/A	≤5%	>2%	No		-92.79521559	45.15360374	FALSE
990	Square Lake	Yes	Yes	No	N/A	≤5%	>2%	No		-92.79537795	45.15346766	FALSE
991	Square Lake	Yes	Yes	No	N/A	≤5%	>2%	No		-92.79570845	45.15310598	FALSE
992	Square Lake	Yes	No	No	N/A	>5%	≤2%	No		-92.79502524	45.15417798	FALSE
993	Square Lake	Yes	Yes	Yes	N/A	≤5%	≤2%	No		-92.79438456	45.15473275	TRUE
298	St. Croix Bluffs	Yes	Yes	N/A	N/A	≤5%	>2%	No	Cross 5.4	-92.79568233	44.80067456	FALSE
300	St. Croix Bluffs	Yes	Yes	Yes	Yes	≤5%	>2%		Poor condition	-92.79525356	44.80107191	FALSE
303	St. Croix Bluffs	Yes	Yes	Yes	N/A	>5%	≤2%	No		-92.79449123	44.80111353	FALSE
304	St. Croix Bluffs	Yes	Yes	Yes	N/A	>5%	>2%	Yes	8.4 cross	-92.79402855	44.80131009	FALSE
305	St. Croix Bluffs	Yes	Yes	Yes	N/A	≤5%	≤2%	Yes		-92.79351474	44.80107506	FALSE

Boat Dock Self Evaluation Results - Parks

OBJECTID	B1	B2	B3	B4	B5	B6	B7	B8	B9	B10	B11	B12	B13	B14	B15	Comment	x	y	ADA Compliant
1	Yes	Yes	Yes	Yes	N/A	Yes	N/A	Yes	N/A	N/A	N/A	N/A	10	No	Yes	Transitional plates in poor condition	-92.79634648	45.15269028	TRUE
2	Yes	No	Yes	Yes	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	N/A	N/A		-92.86990165	45.20405516	FALSE
3	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	N/A	Yes	Yes	Yes	0	Yes	N/A		-92.78729401	44.798811	TRUE
4	Yes	Yes	N/A	Yes	N/A	Yes	N/A	Yes	N/A	N/A	Yes	N/A	6.7	No	Yes	Neither dock is accessible due to gravel	-92.88560009	44.98704979	TRUE

Designated Campsite Self Evaluation Results - Parks

OBJECTID	C1	C2	C3	C4	C5	C6	C7	C8	C9	C10	Comment	x	y	ADA Compliant
1	Yes	Yes	Yes	Yes	Yes	Yes	No	Yes	Yes	No		-92.79075525	44.80376498	FALSE
2	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	No		-92.78998604	44.8036794	FALSE
3	Yes	Yes	Yes	Yes	Yes	No	No	No	Yes	No	Needs updating	-92.79021101	44.80345078	FALSE
4	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes		-92.79032308	44.80306643	TRUE
5	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes		-92.8967741	44.98170686	TRUE
6	Yes	Yes	Yes	Yes	Yes	Yes	No	Yes	Yes	Yes		-92.89644987	44.98192056	FALSE

Fishing Pie Self Evaluation Results - Parks

OBJECTID	F1	F2	F3	F4	F5	F6	F7	F8	F9	F10	Comment	x	y	ADA Compliant
1	No	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes		-92.79502272	45.15502474	FALSE
2	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Path to fishing pier needs reconstruction	-92.87243782	45.20592383	TRUE
4	No	Yes	N/A	Yes	Yes	Yes	Yes	Yes	N/A	Yes		-92.80561477	44.74875749	FALSE
6	Yes	Yes	N/A	N/A	Yes	Yes	Yes	Yes	N/A	Yes	Dock underwater	-92.78840661	44.79871906	TRUE
7	Yes	Yes	No	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Dock tilted	-92.90161272	44.80625775	FALSE
8	Yes	No	N/A	Yes	Yes	Yes	Yes	Yes	N/A	Yes	34" railings are questionable	-92.88872213	44.98065108	FALSE

ORAR Self Evaluation Results - Parks

OBJECTID	O2	O3	O4	O5	O6	O7	O8	O9	O10	O11	O12	O13	O14	Comment	x	y	Running Slope Assessed	Cross Slope Assessed	ADA Compliant
														Mole tunnels are creating some unstable ground. Half of route is complete other is left as grass					
1	N/A	Grass	Yes	Yes	Yes	Yes	0	Yes	0	6.1	10	1.4	Yes		-92.87273336	45.2057776	accessible	accessible	TRUE
2	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	10.5	15	1	Yes		-92.83771377	45.12079376	accessible	accessible	TRUE
3	N/A	Dirt/gravel	Yes	Yes	Yes	Yes	0	Yes	0	0.2	0	0.4	Yes		-92.83769474	45.12085883	accessible	accessible	TRUE
4	N/A	Gravel	Yes	Yes	Yes	Yes		Yes		11.2	50	7.6	Yes		-92.89989769	44.80573536	NOT	NOT	FALSE
5	Asphalt		Yes	Yes	Yes	Yes		Yes		10.2	100	9.1			-92.7935771	45.15450186	NOT	NOT	FALSE
6	Asphalt		Yes	Yes	Yes	Yes		Yes		22.6	50	6.5	Yes	Very steep and bumpy	-92.79415444	45.15441046	NOT	NOT	FALSE
7	N/A	Dirt	Yes	Yes	Yes	Yes		Yes		3.2		0.1	Yes	Dirt connects to asphalt	-92.79485157	45.15411516	accessible	accessible	TRUE
8	N/A	Gravel	Yes	Yes	Yes	Yes	0	Yes		0.4		5.1	Yes		-92.79505433	45.1545716	accessible	NOT	FALSE
9	N/A	Gravel	Yes	Yes	Yes	Yes		Yes		2.3		3.3	Yes		-92.79495098	45.15499694	accessible	accessible	TRUE
10	Boardwalk	Gravel and boardwalk								1.7		0.7			-92.91215563	44.98107362	accessible	accessible	TRUE
11		Gravel								8	50	0.9			-92.90887957	44.97787387	NOT	accessible	FALSE

ORT Self Evaluation Results - Parks

OBJECTID	O2	O3	O4	O5	O6	O7	O8	O9	O10	O11	O12	O13	O14	O15	O16	O17	O18	O19	O20	O21	O22	Comment	x	y	Running Slope Assessed	Cross Slope Assessed	ADA Compliant
1	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	13.5	6	4.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.87413381	45.20416154	accessible	accessible	TRUE
2	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	7.2	15	9.7	No	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.87474753	45.20536937	accessible	NOT	FALSE
3	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	1	0	0.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	One end of bridge has a 2" lip on it. Also just passed bridge to west there is a huge dip that a wheelchair could get stuck in because grades change so quickly	-92.87513478	45.20489332	accessible	accessible	TRUE
4	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	0.9	0	6.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.87531365	45.20416154	accessible	NOT	FALSE
5	N/A	Dirt	Yes	Yes	N/A	Yes	0	Yes	0	1.2	0	3.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.87530476	45.20341194	accessible	accessible	TRUE
6	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	12.6	4	5.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.87526746	45.20294436	accessible	NOT	FALSE
7	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	20.8	20	5.2	Yes	No	No	No	N/A	N/A	N/A	N/A	N/A		-92.87034838	45.20275116	accessible	NOT	FALSE
8	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	0.5	0	2.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.80106893	44.80175265	accessible	accessible	TRUE
9	N/A	Dirt	Yes	Yes	N/A	Yes	0	Yes	0	12.7	40	2.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.80112014	44.8009878	NOT	accessible	FALSE
10	N/A	Dirt	Yes	Yes	N/A	Yes	0	Yes	0	4.5	0	5.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.80036887	44.80073086	accessible	NOT	FALSE
11	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	2.1	0	1.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.79921854	44.80047353	accessible	accessible	TRUE
16	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	3.6	0	5.3	Yes	No	N/A	Yes	No	No	No	No	No		-92.79915249	44.7974819	accessible	NOT	FALSE
17	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	9.2	50	0.3	Yes	No	N/A	Yes	No	No	No	No	No		-92.80033115	44.79748086	NOT	accessible	FALSE
18	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	4.8	0	3.2	Yes	No	N/A	Yes	No	No	No	No	No		-92.80125283	44.79771287	accessible	accessible	FALSE
19	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	1.6	0	0.2	Yes	No	N/A	Yes	No	No	No	No	No		-92.80216126	44.79743773	accessible	accessible	FALSE
20	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	1.2	0	1.5	Yes	No	N/A	Yes	No	No	No	No	No		-92.80317237	44.79621205	accessible	accessible	FALSE
21	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	24	200	1.7	Yes	No	N/A	Yes	No	No	No	No	No		-92.80278948	44.79702421	NOT	accessible	FALSE
22	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	1.8	0	4	Yes	No	N/A	Yes	No	No	No	No	No		-92.80198541	44.79568088	accessible	accessible	FALSE
23	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	1.6	0	3.1	Yes	No	N/A	Yes	No	No	No	No	No		-92.80121938	44.79495266	accessible	accessible	FALSE
24	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	3.7	0	1.9	Yes	No	N/A	Yes	No	No	No	No	No		-92.80009889	44.79479814	accessible	accessible	FALSE
25	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	3.1	0	3.2	Yes	No	N/A	Yes	No	No	No	No	No		-92.79834623	44.79482668	accessible	accessible	FALSE
26	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	1.8	0	8	Yes	No	N/A	Yes	No	No	No	No	No		-92.79674378	44.79483213	accessible	NOT	FALSE
27	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	1.3	0	2	Yes	No	N/A	Yes	No	No	No	No	No		-92.7962702	44.79524394	accessible	accessible	FALSE
33	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	2.2	0	2.6	Yes	Yes	No	Yes	No	No	No	No	No		-92.79612721	44.79594688	accessible	accessible	FALSE
35	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	0.5	0	1	Yes	No	N/A	Yes	No	No	No	No	No		-92.79481829	44.7960276	accessible	accessible	FALSE
36	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	4.2	0	2.3	Yes	No	N/A	Yes	No	No	No	No	No		-92.79374616	44.79605535	accessible	accessible	FALSE
37	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	12.5	50	1	Yes	No	N/A	Yes	No	No	No	No	No		-92.79300084	44.795996	NOT	accessible	FALSE
38	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	0.7	0	4.7	Yes	No	N/A	Yes	No	No	No	No	No		-92.79159738	44.79617801	accessible	accessible	FALSE
39	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	1.9	0	9.5	Yes	No	N/A	Yes	No	No	No	No	No		-92.79190835	44.79645642	accessible	NOT	FALSE
40	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	3.3	0	18.4	Yes	No	N/A	Yes	No	No	No	No	No		-92.79284142	44.79632323	accessible	NOT	FALSE
41	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	0.1	0	10.9	Yes	No	N/A	Yes	No	No	No	No	No		-92.79394356	44.79626632	accessible	NOT	FALSE
43	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	5.7	0	10	Yes	No	N/A	Yes	N/A	N/A	N/A	N/A	N/A		-92.79879098	44.79838233	accessible	NOT	FALSE
44	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	2	0	1.1	Yes	No	N/A	Yes	No	No	No	No	No		-92.79918677	44.79911705	accessible	accessible	FALSE
46	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	4.2	0	2.8	N/A	No	Yes	Yes	No	No	No	No	No		-92.80050566	44.80190185	accessible	accessible	FALSE
47	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	5.1	10	9.8	Yes	No	N/A	Yes	No	No	No	No	No		-92.79938886	44.80205042	accessible	NOT	FALSE
48	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	0.4	0	8	Yes	No	N/A	Yes	No	No	No	No	No		-92.79850323	44.80162856	accessible	NOT	FALSE
49	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	1.8	0	11.1	Yes	No	N/A	Yes	No	No	No	No	No		-92.79777266	44.80120359	accessible	NOT	FALSE
50	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	14.8	20	2.6	Yes	No	N/A	Yes	No	No	No	No	No		-92.79706372	44.80055081	accessible	accessible	FALSE
51	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	0.5	0	9.5	Yes	No	N/A	Yes	No	No	No	No	No		-92.79684319	44.79989116	accessible	NOT	FALSE
52	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	5.8	40	6.1	Yes	No	N/A	Yes	No	No	No	No	No		-92.79161716	44.80489964	NOT	NOT	FALSE
53	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	0.2	0	3.4	Yes	No	N/A	Yes	No	No	No	No	No		-92.79159889	44.80608496	accessible	accessible	FALSE
54	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	3.9	0	5.6	Yes	No	N/A	Yes	No	No	No	No	No		-92.79186443	44.80722033	accessible	NOT	FALSE
55	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	4.7	0	1.3	Yes	No	N/A	Yes	No	No	No	No	No		-92.79084158	44.80819574	accessible	accessible	FALSE
56	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	1.3	0	5.1	Yes	No	N/A	Yes	No	No	No	No	No		-92.78960492	44.80776482	accessible	NOT	FALSE
57	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	7.1	60	1.8	Yes	No	N/A	Yes	No	No	No	No	No		-92.7904794	44.80678523	NOT	accessible	FALSE
58	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	4.5	0	4	Yes	No	N/A	Yes	No	No	No	No	No		-92.79134181	44.80607486	accessible	accessible	FALSE
59	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	6.7	60	4.6	Yes	No	N/A	Yes	No	No	No	No	No		-92.79091241	44.80504699	NOT	accessible	FALSE
60	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2.8	2.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.79556249	44.79909038	accessible	accessible	TRUE
61	N/A	Dirt	Yes	Yes	No	Yes	Yes	Yes	Yes	9.8	30	0.9	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.79518651	44.79884241	NOT	accessible	FALSE
62	N/A	Dirt	Yes	Yes	No	Yes	Yes	Yes	Yes	26.3	30	3.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.79456063	44.79897376	NOT	accessible	FALSE
63	N/A	Dirt	Yes	Yes	No	Yes	Yes	Yes	Yes	13	60	3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.79417096	44.79931012	NOT	accessible	FALSE
64	N/A	Dirt	Yes	Yes	No	Yes	Yes	Yes	Yes	2	5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.79393693	44.79952017	accessible	accessible	FALSE
65	N/A	Dirt	Yes	Yes	No	Yes	Yes	Yes	Yes	5.4	20	15	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.79375714	44.79931272	accessible	NOT	FALSE
66	N/A	Dirt	Yes	Yes	No	Yes	Yes	Yes	Yes	18	20	7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.79323512	44.79924462	accessible	NOT	FALSE
67	N/A	Dirt	Yes	Yes	No	Yes	Yes	Yes	Yes	4.1	4.5	Yes	No														

ORT Self Evaluation Results - Parks

OBJECTID	O2	O3	O4	O5	O6	O7	O8	O9	O10	O11	O12	O13	O14	O15	O16	O17	O18	O19	O20	O21	O22	Comment	x	y	Running Slope Assessed	Cross Slope Assessed	ADA Compliant
71	N/A	Dirt	Yes	Yes	No	Yes	Yes	Yes	5	0	0	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.792467	44.7998829	accessible	accessible	FALSE
72	N/A	Dirt	Yes	Yes	No	Yes	Yes	Yes	4.1	0	3.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.79261595	44.7998078	accessible	accessible	FALSE
73	N/A	Gravel	Yes	Yes	Yes	Yes	Yes	Yes	9.9	5	5.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.79292524	44.8009518	accessible	NOT	FALSE
74	N/A	Gravel	Yes	Yes	Yes	Yes	Yes	Yes	5	0	0	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.79235309	44.80074582	accessible	accessible	TRUE
76	N/A	Gravel	Yes	Yes	Yes	Yes	Yes	Yes	18	200	5.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.79202804	44.79970185	NOT	NOT	FALSE
77	N/A	Gravel	Yes	Yes	Yes	Yes	Yes	Yes	7.1	50	2.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.79137257	44.79942374	NOT	accessible	FALSE
78	N/A	Gravel	Yes	Yes	Yes	Yes	Yes	Yes	21	150	6.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.79060957	44.79926415	NOT	NOT	FALSE
79	N/A	Gravel	Yes	Yes	Yes	Yes	Yes	Yes	9.5	20	6	Yes	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A	N/A		-92.78976032	44.79951062	accessible	NOT	FALSE
80	N/A	Gravel	Yes	Yes	Yes	Yes	Yes	Yes	15.1	50	6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.78928087	44.79933133	NOT	NOT	FALSE
81	N/A	Gravel	Yes	Yes	Yes	Yes	Yes	Yes	4.9	0	2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.78815384	44.7992468	accessible	accessible	TRUE
82	N/A	Gravel	Yes	Yes	Yes	Yes	Yes	Yes	8.5	25	1.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.78762176	44.79895347	accessible	accessible	TRUE
83	N/A	Dirt/rock	Yes	Yes	Yes	Yes	Yes	Yes	0.6	0	2.9	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.78681366	44.79918967	accessible	accessible	TRUE
84	N/A	Dirt/rock	Yes	Yes	Yes	Yes	Yes	Yes	0.5	0	0.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.78680025	44.79880201	accessible	accessible	TRUE
85	N/A	Dirt/rock	Yes	Yes	Yes	Yes	Yes	Yes	0	0	2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.78665926	44.79998503	accessible	accessible	TRUE
86	N/A	Dirt/rock	Yes	Yes	Yes	Yes	Yes	Yes	1.5	0	5.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.78651736	44.80104417	accessible	NOT	FALSE
87	N/A	Rocks	Yes	Yes	Yes	Yes	Yes	Yes	2.5	0	3.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.78647478	44.80213575	accessible	accessible	TRUE
88	N/A	Rocks	Yes	Yes	Yes	Yes	Yes	Yes	1.6	0	1.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.7864586	44.80311039	accessible	accessible	TRUE
89	N/A	Dirt/rock	Yes	Yes	Yes	Yes	Yes	Yes	0.4	0	3.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.78646447	44.80382072	accessible	accessible	TRUE
90	N/A	Dirt/rock	Yes	Yes	Yes	No	Yes	Yes	4.6	0	3.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A	Tree down on trail	-92.78645072	44.80469143	accessible	accessible	FALSE
91	N/A	Gravel	Yes	Yes	Yes	Yes	Yes	Yes	11.2	200	1.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.7876386	44.79970022	NOT	accessible	FALSE
92	N/A	Gravel	Yes	Yes	Yes	Yes	Yes	Yes	26.7	200	6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.78763096	44.80005232	NOT	NOT	FALSE
93	N/A	Gravel	Yes	Yes	Yes	Yes	Yes	Yes	13	200	4.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.78831385	44.80054641	NOT	accessible	FALSE
94	N/A	Gravel	Yes	Yes	Yes	Yes	Yes	Yes	7.9	150	3.9	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.78909546	44.80086379	NOT	accessible	FALSE
95	N/A	Gravel	Yes	Yes	Yes	Yes	Yes	Yes	0.6	0	2.9	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.78831108	44.79986379	accessible	accessible	TRUE
96	N/A	Gravel	Yes	Yes	Yes	Yes	Yes	Yes	2.3	0	0.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.7888088	44.80032056	accessible	accessible	TRUE
97	N/A	Gravel	Yes	Yes	Yes	Yes	Yes	Yes	7.3	100	5.4	Yes	No	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		-92.78949704	44.80129663	NOT	NOT	FALSE
98	N/A	Gravel	Yes	Yes	Yes	Yes	Yes	Yes	11	200	6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.79004807	44.80136461	NOT	NOT	FALSE
99	N/A	Gravel	Yes	Yes	Yes	Yes	Yes	Yes	15.8	100	2	Yes	No	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Ends at set of stairs	-92.78984573	44.80098437	NOT	accessible	FALSE
100	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes	4	0	0.7	Yes	No	N/A	Yes	No	No	No	No	No	No		-92.79031319	44.80173048	accessible	accessible	FALSE
101	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes	5.4	20	8.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.78992016	44.80194937	accessible	NOT	FALSE
102	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes	19.3	30	9.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.78907644	44.80211152	NOT	NOT	FALSE
103	N/A	Dirt	Yes	Yes	No	Yes	Yes	Yes	5.2	0	8.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.78841888	44.80233985	accessible	NOT	FALSE
104	N/A	Dirt	Yes	Yes	No	Yes	Yes	Yes	9.2	200	7.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.78768202	44.80184129	NOT	NOT	FALSE
105	N/A	Dirt	Yes	Yes	No	Yes	Yes	Yes	1.2		1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.78731749	44.80128104	accessible	accessible	FALSE
106	N/A	Dirt	Yes	Yes	No	Yes	Yes	Yes	9.2	150	1.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.78764925	44.80072729	NOT	accessible	FALSE
107	N/A	Dirt	Yes	Yes	No	No	Yes	Yes	9	200	2.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A	Slope is full of roots and rocks	-92.78778001	44.80042047	NOT	accessible	FALSE
108	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes	2.3	0	0.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.79078165	44.80168124	accessible	accessible	TRUE
109	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes	6.2	20	1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.79165605	44.8017835	accessible	accessible	TRUE
110	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes	11	10	8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.79218813	44.80234295	accessible	NOT	FALSE
111	N/A	Dirt	Yes	No	Yes	Yes	Yes	Yes	1	0	2.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A	Bridge not wide enough	-92.7925789	44.80206647	accessible	accessible	FALSE
112	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes	4.3		5.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.7922054	44.80214727	accessible	NOT	FALSE
113	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes	2	0	5.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.79097821	44.8064308	accessible	NOT	FALSE
114	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes	13.2	50	7.9	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.79045844	44.80634677	NOT	NOT	FALSE
115	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes	25.3	25	9	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.78985947	44.80596385	accessible	NOT	FALSE
116		Dirt	Yes	Yes	Yes	Yes	Yes	Yes	4.3		2.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.78991622	44.80542757	accessible	accessible	TRUE
117	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes	1.8		5.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.78994061	44.80517276	accessible	NOT	FALSE
118	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes	9.8	50	7.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.78955119	44.80510751	NOT	NOT	FALSE
119	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes	9.4	25	2.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.78889229	44.80551131	accessible	accessible	TRUE
120	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes	7.6	200	11.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.78799752	44.80558301	NOT	NOT	FALSE
121	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes	8.5	100	11	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.78753065	44.80474378	NOT	NOT	FALSE
122	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes	5	0	1.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.78799609	44.80406061	accessible	accessible	TRUE
123	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes	3.5		4.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.79205017	44.80391606	accessible	accessible	TRUE
124	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes	0.5	0	5.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.79220987	44.80348194	accessible	NOT	FALSE
125	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes	1.8	0	1.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.79214941	44.80285709	accessible	accessible	TRUE
126	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes	3.4	0	4.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.79166913	44.80293048	accessible	accessible	TRUE
127	N/A	Dirt	Yes	Yes	Yes	Yes	0 Yes	0 Yes	0	4.8	0	10	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89994353	44.9876957	accessible	NOT	FALSE
128	N/A	Dirt	Yes	Yes	Yes	Yes	0 Yes	0 Yes	0	0.2	0	8.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90090075	44.98666737	accessible	NOT	FALSE
129	N/A	Dirt	Yes	Yes	Yes	Yes	0 Yes	0 Yes	0	13.7	30	0	Yes	No	N/A	No	No	No	No	No	No		-92.90077309	44.98562411	NOT	accessible	FALSE
130	N/A	Dirt	Yes	Yes	Yes	Yes	0 Yes	0 Yes	0	7.2	30	1.1	Yes	No	N/A	No	No	N/A	N/A	N/A	N/A		-92.90235124	44.98526503	NOT	accessible	FALSE
131	N/A	Dirt	Yes	Yes	Yes	Yes	0 Yes	0 Yes	0	1.4	0	1.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89863973	44.98963175	accessible	accessible	TRUE
132	N/A	Dirt	Yes	Yes	Yes	Yes	0 Yes	0 Yes	0	1.9	0	0	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89843228	44.99082613	accessible	accessible	TRUE

ORT Self Evaluation Results - Parks

OBJECTID	O2	O3	O4	O5	O6	O7	O8	O9	O10	O11	O12	O13	O14	O15	O16	O17	O18	O19	O20	O21	O22	Comment	x	y	Running Slope Assessed	Cross Slope Assessed	ADA Compliant
133	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	4.8	0	1.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89848014	44.99221807	accessible	accessible	TRUE
134	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	3.1	0	3.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89834402	44.99314444	accessible	accessible	TRUE
135	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	0.5	0	0.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89832851	44.99416033	accessible	accessible	TRUE
136	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	0.6	0	1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89834435	44.99490711	accessible	accessible	TRUE
137	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	19	25	1.6	Yes	Yes	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89842306	44.99585481	accessible	accessible	TRUE
138	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	0.5	0	4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89911934	44.9959326	accessible	accessible	TRUE
139	N/A	Dirt	Yes	Yes	Yes	Yes	0	N/A	0	4.6	0	5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90022039	44.99587656	accessible	accessible	TRUE
140	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	18.8	25	0.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90188755	44.99584597	accessible	accessible	TRUE
141	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	0.9	0	7.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90376593	44.99577644	accessible	NOT	FALSE
142	N/A	Dirt	Yes	Yes	N/A	Yes	0	Yes	0	1.6	0	13.9	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90451645	44.99575113	accessible	NOT	FALSE
143	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	8.7	10	4.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90501375	44.99564476	accessible	accessible	TRUE
144	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	6.5	30	7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90660614	44.99559196	NOT	NOT	FALSE
145	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	1.9	0	0.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.9083593	44.99549867	accessible	accessible	TRUE
146	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	3.2	0	11.9	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91031882	44.99534708	accessible	NOT	FALSE
147	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	5.3	20	4.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91181857	44.99444385	accessible	accessible	TRUE
148	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	2	0	5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91091721	44.99364933	accessible	accessible	TRUE
149	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	0.1	0	15	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.9111172	44.99278813	accessible	NOT	FALSE
150	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	11.7	20	6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.9124868	44.99269781	accessible	NOT	FALSE
151	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	4.1	0	2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91297513	44.99213526	accessible	accessible	TRUE
152	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	5.5	20	10.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91283683	44.99127582	accessible	NOT	FALSE
153	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	1.2	0	6.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.9123055	44.99036877	accessible	NOT	FALSE
154	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	0.4	0	1.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91329532	44.98999012	accessible	accessible	TRUE
155	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	6.1	15	5.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91325861	44.98892399	accessible	NOT	FALSE
156	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	2	0	1.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91372917	44.98866649	accessible	accessible	TRUE
157	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	2.2	0	3.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91596806	44.98870945	accessible	accessible	TRUE
158	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	5.1	20	2.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91712618	44.98870756	accessible	accessible	TRUE
159	N/A	Dirt	Yes	Yes	N/A	Yes	0	Yes	0	8.5	20	2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91854834	44.9886758	accessible	accessible	TRUE
160	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	20	30	0.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91896408	44.98805818	NOT	accessible	FALSE
161	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	6	100	0.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91995524	44.98741516	NOT	accessible	FALSE
162	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	1.1	0	0.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.92150866	44.98725565	accessible	accessible	TRUE
163	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	6.5	50	3.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.9226377	44.98683848	NOT	accessible	FALSE
164	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	23	300	7.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.92281264	44.98641939	NOT	NOT	FALSE
165	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	1.5	0	2.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.92329468	44.9857076	accessible	accessible	TRUE
166	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	2.7	0	3.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.92381478	44.98513428	accessible	accessible	TRUE
167	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	10	30	3.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.92551219	44.98509597	NOT	accessible	FALSE
168	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	8	40	10	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.92674635	44.98503164	NOT	NOT	FALSE
169	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	0.5	0	4.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.92808192	44.98497095	accessible	accessible	TRUE
170	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	3	0	5.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.92896613	44.98505113	accessible	NOT	FALSE
171	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	2.2	0	1.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.93023364	44.98519479	accessible	accessible	TRUE
172	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	18.6	40	9.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.93182192	44.98504903	NOT	NOT	FALSE
173	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	10.2	50	3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.9324701	44.98373399	NOT	accessible	FALSE
174	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	13.7	50	2.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.93241729	44.98273047	NOT	accessible	FALSE
175	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	3.6	0	5.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.93212015	44.98173332	accessible	NOT	FALSE
176	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	8.1	60	1.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.93191287	44.98073394	NOT	accessible	FALSE
177	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	1.2	0	1.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.93195394	44.97978809	accessible	accessible	TRUE
178	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	1.6	0	1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.93215536	44.97891377	accessible	accessible	TRUE
179	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	16.6	80	8.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.92343223	44.98461724	NOT	NOT	FALSE
180	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	1.8	0	3.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.92343415	44.98421721	accessible	accessible	TRUE
181	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	0.7	0	0.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.92447041	44.98393923	accessible	accessible	TRUE
182	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	3.5	0	4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.92566936	44.98357243	accessible	accessible	TRUE
183	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	18.2	20	10.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.92610865	44.98309978	accessible	NOT	FALSE
184	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	3.2	0	2.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.92703577	44.98206859	accessible	accessible	TRUE
185	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	4.6	0	1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.92708221	44.98115027	accessible	accessible	TRUE
186	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	0.9	0	1.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.92568017	44.98017873	accessible	accessible	TRUE
187	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	2.3	0	6.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.92448943	44.97937285	accessible	NOT	FALSE
188	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	6.8	15	7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.92360778	44.97846113	accessible	NOT	FALSE
189	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	0.7	0	0.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.93114048	44.97841061	accessible	accessible	FALSE
190	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	3.2	0	2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.93001328	44.97828266	accessible	accessible	TRUE
191	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	3.2	0	2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.92888283	44.9782105	accessible	accessible	TRUE
192	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	0.4	0	0.9	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.92757012	44.97828215	accessible	accessible	TRUE
193	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	5	0	4.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.926988	44.97824984	accessible	accessible	TRUE

ORT Self Evaluation Results - Parks

OBJECTID	O2	O3	O4	O5	O6	O7	O8	O9	O10	O11	O12	O13	O14	O15	O16	O17	O18	O19	O20	O21	O22	Comment	x	y	Running Slope Assessed	Cross Slope Assessed	ADA Compliant
194	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	3.3	0	3.4	Yes	No	N/A	N/A	N/A	N/A	N/A	N/A	N/A		-92.92558285	44.97827562	accessible	accessible	TRUE
195	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	0.8	0	4.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.9242555	44.97823002	accessible	accessible	TRUE
196	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	3	0	2.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.92245867	44.9780874	accessible	accessible	TRUE
197	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3.6		4.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.92117917	44.97832486	accessible	accessible	TRUE
198	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2.8		8.5	Yes	Yes	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.92009447	44.97821833	accessible	NOT	FALSE
199	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3.9		2.2	No	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91890424	44.97850327	accessible	accessible	FALSE
200	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes	Yes	10.5	50	5.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91784292	44.97827264	NOT	NOT	FALSE
201	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes	Yes	10.4	30	11.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91659175	44.97778783	NOT	NOT	FALSE
202	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes	Yes	15.5	30	4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91589438	44.97770657	NOT	accessible	FALSE
203	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1.3		8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91503415	44.97778125	accessible	NOT	FALSE
204	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes	Yes	13	20	1.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91556486	44.97857577	accessible	accessible	TRUE
205	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes	Yes	7.5	15	4.1	Yes	No	N/A	N/A	N/A	N/A	N/A	N/A	N/A		-92.91623603	44.979147	accessible	accessible	TRUE
206	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4.1		6.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91775525	44.97947209	accessible	NOT	FALSE
207	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1.1		6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91930162	44.97998314	accessible	NOT	FALSE
208	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2.6		5.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.92008382	44.98085703	accessible	NOT	FALSE
209	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes	Yes	6.3	100	8.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91964704	44.98142642	NOT	NOT	FALSE
210	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4.7		4.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91989691	44.98160788	accessible	accessible	TRUE
211	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4.2		1.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91998425	44.98266241	accessible	accessible	TRUE
212	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes	Yes	0		8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91999472	44.98349603	accessible	NOT	FALSE
213	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5.6	40	2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.92064189	44.98406252	NOT	accessible	FALSE
214	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes	Yes	13.9	150	7.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.92211736	44.98481333	NOT	NOT	FALSE
215	Asphalt	Yes	Yes	Yes	Yes	0	Yes	0	Yes	2.6	0	4.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.88970632	44.98889585	accessible	NOT	FALSE
216	Asphalt	Yes	Yes	Yes	Yes	0	Yes	0	Yes	1.3	0	1.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.8889811	44.98855727	accessible	accessible	TRUE
217	Asphalt	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2.2	0	1.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.88811371	44.98806758	accessible	accessible	TRUE
218	Asphalt	Yes	Yes	Yes	Yes	0	Yes	0	Yes	6.6	25	4.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.88712063	44.98734085	accessible	NOT	FALSE
219	Asphalt	Yes	Yes	Yes	Yes	0	Yes	0	Yes	1.4	0	1.9	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	Grass growing in grass	-92.88740178	44.98730879	accessible	accessible	TRUE
220	Asphalt	Yes	Yes	Yes	Yes	0	Yes	0	Yes	4.2	0	1.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	Grass growing in cracks	-92.88746967	44.98652894	accessible	accessible	TRUE
221	Asphalt	Yes	Yes	Yes	Yes	0	Yes	0	Yes	4.3	0	6.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.88725669	44.98566992	accessible	NOT	FALSE
222	Asphalt	Yes	Yes	Yes	Yes	0	Yes	0	Yes	1.5	0	3.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.88781215	44.98472662	accessible	NOT	FALSE
223	Asphalt	Yes	Yes	Yes	Yes	0	Yes	0	Yes	2.6	0	0.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.88772993	44.98384321	accessible	accessible	TRUE
224	Asphalt	Yes	Yes	Yes	Yes	0	Yes	0	Yes	4.3	0	1.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.8881248	44.98278223	accessible	accessible	TRUE
225	Asphalt	Yes	Yes	Yes	Yes	0	Yes	0	Yes	3.2	0	2.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.88836821	44.98185452	accessible	NOT	FALSE
226	Asphalt	Yes	Yes	Yes	Yes	0	Yes	0	Yes	3.5	0	4.9	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.88903482	44.98083809	accessible	NOT	FALSE
227	Asphalt	Yes	Yes	Yes	Yes	0	Yes	0	Yes	2.2	0	2.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.88970596	44.98037361	accessible	NOT	FALSE
228	Asphalt	Yes	Yes	Yes	Yes	0	Yes	0	Yes	3.4	0	2.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	Grass growing in cracks	-92.89064348	44.98025077	accessible	NOT	FALSE
229	Asphalt	Yes	Yes	Yes	Yes	0	Yes	0	Yes	9	50	3.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89150086	44.98076881	NOT	NOT	FALSE
230	Asphalt	Yes	Yes	Yes	Yes	0	Yes	0	Yes	2.1	0	0.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89225947	44.98151149	accessible	accessible	TRUE
231	Asphalt	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	0.2	0	0.9	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.8928594	44.98240022	accessible	accessible	TRUE
232	Asphalt	Yes	Yes	Yes	Yes	0	Yes	0	Yes	1.4	0	0.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	Roots popping asphalt up	-92.89316635	44.9832099	accessible	accessible	TRUE
233	Asphalt	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	7.1	30	1.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89401025	44.98354153	NOT	accessible	FALSE
234	Asphalt	Yes	Yes	Yes	Yes	0	Yes	0	Yes	7.2	100	2.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89502081	44.98347076	NOT	NOT	FALSE
235	Asphalt	Yes	Yes	Yes	Yes	0	Yes	0	Yes	1.8	0	1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	Grass growing in cracks	-92.8962505	44.98380104	accessible	accessible	TRUE
236	Asphalt	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	0.5		1.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	Grass growing in cracks	-92.89645239	44.98429236	accessible	accessible	TRUE
237	Asphalt	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1.8		0.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89555033	44.98486446	accessible	accessible	TRUE
238	Asphalt	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	7.2	200	1.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89493904	44.98533502	NOT	accessible	FALSE
239	Asphalt	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	0.5		2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89440524	44.98604565	accessible	accessible	TRUE
240	Asphalt	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1.5		2.2	Yes	No	N/A	Yes	N/A	N/A	N/A	N/A	N/A		-92.89315746	44.98641863	accessible	NOT	FALSE
241	Asphalt	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2.2		2.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	Patch job pretty bumpy	-92.89296359	44.98699405	accessible	NOT	FALSE
242	Asphalt	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2.7		3.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89272211	44.98770224	accessible	NOT	FALSE
243	Asphalt	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	0.8		0.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89162592	44.98803152	accessible	accessible	TRUE
244	Asphalt	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	4.7		2.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	Grass growing in cracks	-92.89135896	44.98763275	accessible	NOT	FALSE
245	Asphalt	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2.4		2.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89135074	44.98713902	accessible	NOT	FALSE
246	Asphalt	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	0.7		3.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.891036	44.98680005	accessible	NOT	FALSE
247	Asphalt	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2.2		0.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89106752	44.9884168	accessible	accessible	TRUE
248	Asphalt	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1.4		1.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89038816	44.98871389	accessible	accessible	TRUE
249	Asphalt	Yes	Yes	Yes	Yes	0	Yes	0	Yes	0	0.2	0	3	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.88691387	44.9876988	accessible	NOT	FALSE
250	Asphalt	Yes	Yes	Yes	Yes	0	Yes	0	Yes	0	4.9	0	3.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.88706031	44.98835313	accessible	NOT	FALSE
251	Asphalt	Yes	Yes	Yes	Yes	0	Yes	0	Yes	0	0.2	0	1.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.88796093	44.98917406	accessible	accessible	TRUE
252	Asphalt	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2.7		1.9	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.88871128	44.98984524	accessible	accessible	TRUE
253	Asphalt	Yes	Yes	Yes	Yes	0	Yes	0	Yes	0.7		1.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.88892913	44.99064785	accessible	accessible	TRUE
254	Asphalt	Yes	Yes	Yes	Yes	0	Yes	0	Yes	3.2	0	1.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.88980635	44.99096553	accessible	accessible	TRUE

ORT Self Evaluation Results - Parks

OBJECTID	O2	O3	O4	O5	O6	O7	O8	O9	O10	O11	O12	O13	O14	O15	O16	O17	O18	O19	O20	O21	O22	Comment	x	y	Running Slope Assessed	Cross Slope Assessed	ADA Compliant
255	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		2.1	0	0.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	Grass growing in cracks	-92.89090265	44.99100349	accessible	accessible	TRUE
256	Asphalt		Yes	Yes	Yes	Yes	0	Yes	0	0.9	0	4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89140908	44.99068821	accessible	NOT	FALSE
257	Asphalt		Yes	Yes	Yes	Yes	0	Yes		0.4	0	1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89135678	44.98985075	accessible	accessible	TRUE
258	Asphalt		Yes	Yes	Yes	Yes	0	Yes		0.1	0	0.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89053543	44.98941466	accessible	accessible	TRUE
259	Asphalt		Yes	Yes	Yes	Yes	0	Yes	0	2.3	0	0.9	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89040049	44.98905403	accessible	accessible	TRUE
260	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		3.2	0	3.4	Yes	Yes	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89121143	44.98876973	accessible	NOT	FALSE
261	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		4.4	0	1.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89221735	44.98852958	accessible	accessible	TRUE
262	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		5.9	150	2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89320875	44.98892663	NOT	accessible	FALSE
263	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		4.9	0	5.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89433942	44.98977962	accessible	NOT	FALSE
264	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		0	0	4.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89584998	44.99027788	accessible	NOT	FALSE
265	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		0.1	0	4.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89714968	44.99012316	accessible	NOT	FALSE
266	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		1.5	0	6.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89772292	44.98977165	accessible	NOT	FALSE
267	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		0.1	0	4.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89757468	44.98890048	accessible	NOT	FALSE
268	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		0.2	0	3.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89815124	44.98815806	accessible	NOT	FALSE
269	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		1	0	3.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89927716	44.98726864	accessible	NOT	FALSE
270	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		0.1	0	2.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89961467	44.98636504	accessible	NOT	FALSE
271	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		1.2	0	3.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89905859	44.98528111	accessible	NOT	FALSE
272	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		0.8	0	4.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.8982085	44.98442933	accessible	NOT	FALSE
273	Asphalt		Yes	Yes	Yes	Yes	0	Yes		2.7	0	4.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89708349	44.98395727	accessible	NOT	FALSE
274	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		0.3	0	1.9	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89572104	44.98416002	accessible	accessible	TRUE
275	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		0.2	0	4.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89526638	44.98437057	accessible	NOT	FALSE
276	Asphalt		Yes	Yes	Yes	Yes	0	Yes		1.4	0	1.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89415192	44.98430536	accessible	accessible	TRUE
277	Asphalt		Yes	Yes	Yes	Yes	0	Yes		1.6	0	0.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89341856	44.98431264	accessible	accessible	TRUE
278	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		0.3	0	1.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.8985715	44.9848029	accessible	accessible	TRUE
279	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		1.5	0	1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89937867	44.98399574	accessible	accessible	TRUE
280	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		2.5	0	4.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90006457	44.98292983	accessible	NOT	FALSE
281	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		0.8	0	0.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90038864	44.98202702	accessible	accessible	TRUE
282	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		4.3	0	1.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90070475	44.98115161	accessible	accessible	TRUE
283	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		0.4	0	2.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90099291	44.98027318	accessible	NOT	FALSE
284	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		0.6	0	3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90200587	44.97909618	accessible	NOT	FALSE
285	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		1.4	0	3.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.9027067	44.97841321	accessible	NOT	FALSE
286	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		1.7	0	2.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90352397	44.97745713	accessible	NOT	FALSE
287	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		0.4	0	3.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90353264	44.97652916	accessible	NOT	FALSE
289	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		3.1	0	2.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.9036475	44.97539203	accessible	NOT	FALSE
290	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		2.9	0	0.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90469229	44.97451545	accessible	accessible	TRUE
291	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		3.8	0	6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90465193	44.97368972	accessible	NOT	FALSE
292	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		2.1	0	4.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90372853	44.97279956	accessible	NOT	FALSE
293	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		1.8	0	3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.9035277	44.97168521	accessible	NOT	FALSE
294	Asphalt		Yes	Yes	N/A	Yes	Yes	Yes		0.4		0.6	Yes	No	N/A	N/A	N/A	N/A	N/A	N/A	N/A		-92.89934729	44.82462464	accessible	accessible	TRUE
295	Asphalt		Yes	Yes	N/A	Yes	Yes	Yes		0.8		2.7	Yes	Yes	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89911769	44.82330067	accessible	NOT	FALSE
296	Asphalt		Yes	Yes	N/A	Yes	Yes	Yes		6.1	100	2.9	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89939875	44.82243822	NOT	NOT	FALSE
297	Asphalt		Yes	Yes	N/A	Yes	Yes	Yes		1.1		0.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89888864	44.81999178	accessible	accessible	TRUE
298	Asphalt		Yes	Yes	N/A	Yes	Yes	Yes		1.3		0.9	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89900478	44.81921296	accessible	accessible	TRUE
299	Asphalt		Yes	Yes	N/A	Yes	Yes	Yes		2.4		4.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90127886	44.81751274	accessible	NOT	FALSE
300	Asphalt		Yes	Yes	N/A	Yes	Yes	Yes		0.9		2.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90219202	44.81651434	accessible	NOT	FALSE
301	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		1.2		5.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90155806	44.82251752	accessible	NOT	FALSE
302	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		14	100	2.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90229985	44.82260372	NOT	NOT	FALSE
303	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		0.2		3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90192259	44.82190015	accessible	NOT	FALSE
304	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		0		2	Yes	Yes	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.79245443	44.80264784	accessible	accessible	TRUE
305	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		1.9		1.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.79348356	44.80241398	accessible	accessible	TRUE
306	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		6.1		3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.79450196	44.80214752	accessible	NOT	FALSE
307	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		12.5	100	0.8	Yes	Yes	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.7955481	44.80214614	NOT	accessible	FALSE
308	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		3		0.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.79697309	44.80202419	accessible	accessible	TRUE
309	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		0.6		1.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.79854652	44.80209312	accessible	accessible	TRUE
310	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		2		0.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.79980365	44.80242561	accessible	accessible	TRUE
311	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		0.7		2	Yes	No	Yes	No	N/A	N/A	N/A	N/A	N/A		-92.80148147	44.80204303	accessible	accessible	TRUE
312	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		1.3		0.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.80257083	44.80163414	accessible	accessible	TRUE
313	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		1.8		2.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.80346446	44.80167913	accessible	NOT	FALSE
314	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		2.8		3.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.83810093	45.12053064	accessible	NOT	FALSE
315	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		4.6		1.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.83855355	45.12016439	accessible	accessible	TRUE
316	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes		15.4	20	1.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.79457777	45.15260927	accessible	accessible	TRUE

ORT Self Evaluation Results - Parks

OBJECTID	O2	O3	O4	O5	O6	O7	O8	O9	O10	O11	O12	O13	O14	O15	O16	O17	O18	O19	O20	O21	O22	Comment	x	y	Running Slope Assessed	Cross Slope Assessed	ADA Compliant
317	Asphalt		Yes	Yes	Yes	Yes		Yes		2.4		2	Yes	Yes	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.88318682	45.20272122	accessible	accessible	TRUE
318	Asphalt		Yes	Yes	Yes	Yes		Yes		6.6	20	1.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.87958896	45.20184437	accessible	accessible	TRUE
319	Asphalt		Yes	Yes	Yes	Yes		Yes		5.6	75	0.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.87128933	45.20244848	NOT	accessible	FALSE
321	Asphalt		Yes	Yes	Yes	Yes		Yes		1.4		1.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.87256891	45.20255296	accessible	accessible	TRUE
322	Asphalt		Yes	Yes	Yes	Yes		Yes		1.6		0.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.87477366	45.20287718	accessible	accessible	TRUE
323	Asphalt		Yes	Yes	N/A	Yes		0 Yes		0	4.4	0	2.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.88066767	45.20187669	accessible	NOT	FALSE
324	Asphalt		Yes	Yes	N/A	Yes		0 Yes		0	5.2	100	4.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.88170683	45.20249189	NOT	NOT	FALSE
325	Asphalt		Yes	Yes	Yes	Yes		0 Yes		0	0.2	0	0.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.87346845	45.20296664	accessible	accessible	TRUE
326	Asphalt		Yes	Yes	N/A	Yes		0 Yes		0	3.4	0	2.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.87709124	45.20224807	accessible	NOT	FALSE
327	Asphalt		Yes	Yes	N/A	Yes		0 Yes		0	0.5	0	1.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.87842017	45.2017263	accessible	accessible	TRUE
328	Asphalt		Yes	Yes	N/A	Yes		0 Yes		0	1.2	0	3.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.87997535	45.20148776	accessible	NOT	FALSE
329	Asphalt		Yes	Yes	Yes	Yes		0 Yes		0	0.4	0	0.6	No	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.90004227	44.82515037	accessible	accessible	FALSE
330	Asphalt		Yes	Yes	Yes	Yes		Yes		1.6		0.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90238427	44.81559996	accessible	accessible	TRUE
331	Asphalt		Yes	Yes	Yes	Yes		Yes		2.4		1.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90462921	44.81263333	accessible	accessible	TRUE
332	Asphalt		Yes	Yes	Yes	Yes		N/A		1.4		1.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90507488	44.81092536	accessible	accessible	TRUE
333	Asphalt		Yes	Yes	Yes	Yes		Yes		1.1		1.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90473858	44.81006087	accessible	accessible	TRUE
334	Asphalt		Yes	Yes	N/A	Yes		Yes		0		1.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.9045414	44.80905912	accessible	accessible	TRUE
335	Asphalt		Yes	Yes	N/A	Yes		Yes		1.4		0.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90388821	44.8086363	accessible	accessible	TRUE
336	Asphalt		Yes	Yes	N/A	Yes		Yes		2		1.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90285246	44.80843924	accessible	accessible	TRUE
337	Asphalt		Yes	Yes	N/A	Yes		Yes		0.8		0.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90177206	44.80711277	accessible	accessible	TRUE
338	Asphalt		Yes	Yes	N/A	Yes		Yes		0.8		0.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90132842	44.80654658	accessible	accessible	TRUE
339	Asphalt		Yes	Yes	N/A	Yes		Yes		1.1		2.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90111674	44.80622264	accessible	NOT	FALSE
340	Asphalt		Yes	Yes	No	Yes		Yes		4.5		0.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89327607	44.9819054	accessible	accessible	FALSE
341	Asphalt		Yes	Yes	No	Yes		Yes		0.7		4.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89403086	44.98151275	accessible	NOT	FALSE
342	Asphalt		Yes	Yes	No	Yes		Yes		12.1	10	1.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	Cracks and sink holes forming on path	-92.89448147	44.98135785	accessible	accessible	FALSE
343	Asphalt		Yes	Yes	No	Yes		Yes		2.2		1.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89585426	44.9812501	accessible	accessible	FALSE
344	Asphalt		Yes	Yes	No	Yes		0 Yes		0	7.1	15	4.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.89509108	44.98128007	accessible	NOT	FALSE
345	Asphalt		Yes	Yes	No	Yes		Yes		6.2	25	0.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89553843	44.9816961	accessible	accessible	FALSE
346	Asphalt		Yes	Yes	No	Yes		0 Yes		0	1.1		0.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.89607579	44.98144104	accessible	accessible	FALSE
347	Asphalt		Yes	Yes	No	Yes		Yes		0		0.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89648256	44.98153991	accessible	accessible	FALSE
348	Asphalt		Yes	Yes	No	Yes		0 Yes		0	4.9	0	1.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.89679185	44.98191298	accessible	accessible	FALSE
349	Asphalt		Yes	Yes	No	Yes		Yes		14.4		2.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89665045	44.98220715	accessible	NOT	FALSE
350	Asphalt		Yes	Yes	No	Yes		Yes		1.3		3.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89673695	44.98140957	accessible	NOT	FALSE
351	Asphalt		Yes	Yes	No	Yes		Yes		0.4		1.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89724087	44.9815684	accessible	accessible	FALSE
352	Asphalt		Yes	Yes	No	Yes		Yes		0.4		0.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89806171	44.98156627	accessible	accessible	FALSE
353	Asphalt		Yes	Yes	No	Yes		Yes		0.5		4.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89836966	44.98169321	accessible	NOT	FALSE
354	Asphalt		Yes	Yes	No	Yes		Yes		6.7	20	1.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89806264	44.98142046	accessible	accessible	FALSE
355	N/A	Turf	Yes	Yes	N/A	No		Yes		13.1	100	7.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89900769	44.82087353	NOT	NOT	FALSE
356	N/A	Turf	Yes	Yes	N/A	Yes		0 Yes		13.6	100	13.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89944506	44.82028957	NOT	NOT	FALSE
357	N/A	Grass	Yes	Yes	N/A	Yes		Yes		5.8	200	0.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89954606	44.81964793	NOT	accessible	FALSE
358	N/A	Grass	Yes	Yes	N/A	Yes		Yes		2.8		0.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89966752	44.81916564	accessible	accessible	TRUE
359	N/A	Grass	Yes	Yes	N/A	Yes		Yes		7.9	50	31.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89999844	44.81903056	NOT	NOT	FALSE
360	N/A	Grass	Yes	Yes	N/A	Yes		Yes		0.1		5.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90039197	44.81872806	accessible	NOT	FALSE
361	N/A	Grass	Yes	Yes	N/A	Yes		Yes		3.1		2.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90079606	44.81838562	accessible	accessible	TRUE
362	N/A	Grass	Yes	Yes	N/A	Yes		Yes		15.7	200	2.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90018032	44.8183647	NOT	accessible	FALSE
363	N/A	Grass	Yes	Yes	N/A	Yes		Yes		7.3	200	3.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89948261	44.81816433	NOT	accessible	FALSE
364	N/A	Grass	Yes	Yes	N/A	Yes		Yes		15.9	300	5.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89912194	44.81768661	NOT	NOT	FALSE
365	N/A	Grass	Yes	Yes	N/A	Yes		Yes		15.5	300	0.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89882849	44.81771532	NOT	accessible	FALSE
366	N/A	Grass	Yes	Yes	N/A	Yes		Yes		18.3		1.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89894651	44.8182671	accessible	accessible	TRUE
367	N/A	Grass	Yes	Yes	N/A	Yes		Yes		6.7	200	2.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89883798	44.81880175	NOT	accessible	FALSE
368	N/A	Grass	Yes	Yes	N/A	Yes		Yes		0.8		0.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89834091	44.8192407	accessible	accessible	TRUE
369	N/A	Grass	Yes	Yes	N/A	Yes		Yes		0.7		0.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89791008	44.81993799	accessible	accessible	TRUE
370	N/A	Grass	Yes	Yes	N/A	Yes		Yes		9.7	100	8.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89842633	44.8204342	NOT	NOT	FALSE
371	N/A	Turf	Yes	Yes	N/A	Yes		Yes		4.1		2.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89863948	44.82096133	accessible	accessible	TRUE
372	N/A	Turf	Yes	Yes	N/A	Yes		Yes		1.2		9.9	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89858248	44.82155515	accessible	NOT	FALSE
373	N/A	Turf	Yes	Yes	N/A	Yes		N/A		14.3	300	1.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89865683	44.82230613	NOT	accessible	FALSE
374	N/A	Turf	Yes	No	Yes	Yes		Yes		17.5	200	10.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89929228	44.8224982	NOT	NOT	FALSE
375	N/A	Grass	Yes	Yes	N/A	Yes		Yes		7.9	100	6.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.9010569	44.81826177	NOT	NOT	FALSE
376	N/A	Grass	Yes	Yes	N/A	Yes		Yes		3.3		2.9	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90158748	44.81779675	accessible	accessible	TRUE
377	N/A	Grass	Yes	Yes	N/A	Yes		Yes		2.8		2.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90177582	44.81709996	accessible	accessible	TRUE
378	Asphalt		Yes	Yes	N/A	Yes		Yes		0.1		0.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90354197	44.81433083	accessible	accessible	TRUE

ORT Self Evaluation Results - Parks

OBJECTID	O2	O3	O4	O5	O6	O7	O8	O9	O10	O11	O12	O13	O14	O15	O16	O17	O18	O19	O20	O21	O22	Comment	x	y	Running Slope Assessed	Cross Slope Assessed	ADA Compliant
379	N/A	Turf	Yes	Yes	Yes	Yes	Yes	Yes	14.4	200	1.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.90280562	44.80848986	NOT	accessible	FALSE
380	N/A	Turf	Yes	Yes	Yes	Yes	Yes	Yes	14.2	200	3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.90211101	44.8082959	NOT	accessible	FALSE
381	N/A	Turf	Yes	Yes	Yes	Yes	Yes	Yes	12.5	100	5.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.90134226	44.81211308	NOT	NOT	FALSE
382	N/A	Turf	Yes	Yes	Yes	Yes	Yes	Yes	9.9	150	3.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.90050068	44.80843299	NOT	accessible	FALSE
383	N/A	Turf	Yes	Yes	Yes	Yes	Yes	Yes	10.4	100	4.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.90030111	44.80934347	NOT	accessible	FALSE
384	N/A	Turf	Yes	Yes	Yes	Yes	Yes	Yes	1.1		5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.90004783	44.8104756	accessible	accessible	TRUE
385	N/A	Turf	Yes	Yes	Yes	Yes	Yes	Yes	0.8		1.9	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.90049506	44.81144108	accessible	accessible	TRUE
386	N/A	Turf	Yes	Yes	Yes	Yes	Yes	Yes	3.3		0.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.90225116	44.81305711	accessible	accessible	TRUE
387	N/A	Turf	Yes	Yes	Yes	Yes	Yes	Yes	2.1		1.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.90164213	44.81404522	accessible	accessible	TRUE
388	N/A	Turf	Yes	Yes	Yes	Yes	Yes	Yes	4.6		2.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.9002141	44.81449545	accessible	accessible	TRUE
389	N/A	Turf	Yes	Yes	Yes	Yes	Yes	Yes	1.4		1.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.89928614	44.81476983	accessible	accessible	TRUE
390	N/A	Turf	Yes	Yes	Yes	Yes	Yes	Yes	3.3		1.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.89975159	44.81539826	accessible	accessible	TRUE
391	N/A	Grass	Yes	Yes	Yes	Yes	Yes	Yes	0.6		0.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.8994065	44.8161438	accessible	accessible	TRUE
392	N/A	Grass	Yes	Yes	N/A	Yes	Yes	Yes	1.1		1.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.89927038	44.81689125	accessible	accessible	TRUE
393	N/A	Grass	Yes	Yes	N/A	Yes	Yes	Yes	8.8	200	3.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.90005292	44.81714363	NOT	accessible	FALSE
394	N/A	Grass	Yes	Yes	N/A	Yes	Yes	Yes	21.8	200	3.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.90135832	44.81715276	NOT	accessible	FALSE
395	N/A	Grass	Yes	Yes	Yes	Yes	Yes	Yes	5.1	30	15.2	Yes	Yes	No	Yes	No	No	No	No	No	No		-92.89987254	44.80664672	NOT	NOT	FALSE
396	N/A	Grass	Yes	Yes	Yes	Yes	0	Yes	15	20	3.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.89886395	44.80712252	accessible	accessible	TRUE
397	N/A	Grass	Yes	Yes	Yes	Yes	0	Yes	5.9	50	5.9	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.89827378	44.8078196	NOT	NOT	FALSE
398	N/A	Grass	Yes	Yes	Yes	Yes	0	Yes	17.3	75	5.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.8981804	44.80826681	NOT	NOT	FALSE
399	N/A	Grass	Yes	Yes	Yes	Yes	Yes	Yes	6.3	50	4.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.89752904	44.80907139	NOT	accessible	FALSE
400	N/A	Grass	Yes	Yes	Yes	Yes	Yes	Yes	0.6		2.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.89705873	44.80998766	accessible	accessible	TRUE
401	N/A	Turf	Yes	Yes	N/A	Yes	Yes	Yes	0.9		2.6	Yes	No	N/A	No								-92.89726895	44.81102895	accessible	accessible	TRUE
402	N/A	Turf	Yes	Yes	N/A	Yes	Yes	Yes	6.1	10	2.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.89750683	44.81159954	accessible	accessible	TRUE
403	N/A	Turf	Yes	Yes	N/A	Yes	Yes	Yes	0.3		1.2	Yes	No	N/A	No								-92.89698623	44.81261086	accessible	accessible	TRUE
404	N/A	Turf	Yes	Yes	N/A	Yes	Yes	Yes	10.1	200	0.5	Yes	No	N/A	No								-92.89722562	44.81334	NOT	accessible	FALSE
405	N/A	Turf	Yes	Yes	N/A	Yes	Yes	Yes	3.6		6.5	Yes	No	N/A	No								-92.89796591	44.81389543	accessible	NOT	FALSE
406	N/A	Turf	Yes	Yes	N/A	Yes	Yes	Yes	2.5		6.8	Yes	No	N/A	No								-92.89867979	44.81435069	accessible	NOT	FALSE
407	N/A	Turf	Yes	Yes	N/A	Yes	Yes	Yes	4.2		2.4	Yes	No	N/A	No								-92.89903712	44.81690043	accessible	accessible	TRUE
408	N/A	Turf	Yes	Yes	N/A	Yes	N/A	N/A	12.6	200	8.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.89821192	44.81665337	NOT	NOT	FALSE
409	N/A	Turf	Yes	Yes	N/A	Yes	Yes	Yes	0.3		0.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.89723408	44.81589292	accessible	accessible	TRUE
410	N/A	Turf	Yes	Yes	N/A	Yes	Yes	Yes	0		0.2	Yes	No	N/A	No								-92.89683678	44.81508231	accessible	accessible	TRUE
411	N/A	Grass	Yes	Yes	Yes	Yes	Yes	Yes	8.5	200	13.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.89740139	44.81449578	NOT	NOT	FALSE
413	N/A	Grass	Yes	Yes	Yes	Yes	Yes	Yes	6.3	100	5.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.89851727	44.81343145	NOT	NOT	FALSE
414	N/A	Turf	Yes	Yes	N/A	Yes	Yes	Yes	12.3	75	6.5	Yes	No	N/A	No								-92.89800815	44.81266622	NOT	NOT	FALSE
415	N/A	Turf	Yes	Yes	N/A	Yes	Yes	Yes	20	75	9.5	Yes	No	N/A	No								-92.89941313	44.81254921	NOT	NOT	FALSE
416	N/A	Turf	Yes	Yes	N/A	Yes	Yes	Yes	2		4.2	Yes	No	N/A	No								-92.90019122	44.81222835	accessible	accessible	TRUE
417	N/A	Turf	Yes	Yes	N/A	Yes	Yes	Yes	5.6		4.2	Yes	No	N/A	No								-92.90145789	44.81224114	accessible	accessible	TRUE
418	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes	0.8	0	0	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.98691307	45.296216	accessible	accessible	TRUE
419	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes	0.4	0	2.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.9864369	45.2949005	accessible	NOT	FALSE
420	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes	0.4	0	2.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.98589978	45.29340098	accessible	NOT	FALSE
421	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes	0.5		0.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.98543015	45.29152201	accessible	accessible	TRUE
422	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes	0.2		0.9	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.98544406	45.28993208	accessible	accessible	TRUE
423	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes	0.1		2.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.98546912	45.2888465	accessible	NOT	FALSE
424	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes	0.3		2.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.98552972	45.28767199	accessible	NOT	FALSE
425	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes	0.7		1.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.9856241	45.28612402	accessible	accessible	TRUE
426	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes	0		1.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.9856381	45.28501136	accessible	accessible	TRUE
427	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes	0.5		1.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.9856775	45.28378442	accessible	accessible	TRUE
428	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes	0.1		1.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.98575176	45.28280688	accessible	accessible	TRUE
429	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes	0.8		1.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.98578302	45.28168077	accessible	accessible	TRUE
430	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes	0.9		0.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.98587288	45.28116038	accessible	accessible	TRUE
431	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes	4.7		0.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.98594069	45.2798588	accessible	accessible	TRUE
432	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes	4.9		1.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.98598251	45.27873135	accessible	accessible	TRUE
433	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes	0.7		2.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.98603456	45.27766161	accessible	NOT	FALSE
434	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes	0.7		1.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.98606315	45.27638286	accessible	accessible	TRUE
435	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes	0.7		0.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.98605887	45.27524946	accessible	accessible	TRUE
436	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes	0.5		1.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.98611587	45.27404289	accessible	accessible	TRUE
437	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes	1.4		1.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.98616901	45.27248482	accessible	accessible	TRUE
438	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes	0.3		1.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.98621067	45.27112184	accessible	accessible	TRUE
439	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes	5.9	100	1.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.98634369	45.26931885	NOT	accessible	FALSE
440	Asphalt		Yes	Yes	Yes	Yes	Yes	Yes	6	100	1.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.98635677	45.26791857	NOT	accessible	FALSE

ORT Self Evaluation Results - Parks

OBJECTID	O2	O3	O4	O5	O6	O7	O8	O9	O10	O11	O12	O13	O14	O15	O16	O17	O18	O19	O20	O21	O22	Comment	x	y	Running Slope Assessed	Cross Slope Assessed	ADA Compliant
441	Asphalt		Yes	Yes	Yes	Yes		Yes		0		2.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.9864198	45.2668337	accessible	NOT	FALSE
442	Asphalt		Yes	Yes	Yes	Yes		Yes		0		0.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.98649171	45.26518988	accessible	accessible	TRUE
443	Asphalt		Yes	Yes	Yes	Yes		Yes		0.1		0.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.98655441	45.26353064	accessible	accessible	TRUE
444	Asphalt		Yes	Yes	Yes	Yes		Yes		0.9		2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.9865291	45.26264828	accessible	accessible	TRUE
445	Asphalt		Yes	Yes	Yes	Yes		Yes		0		0.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.98633061	45.2609861	accessible	accessible	TRUE
446	Asphalt		Yes	Yes	Yes	Yes		Yes		0.7		1.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.98607999	45.2593759	accessible	accessible	TRUE
447	Asphalt		Yes	Yes	Yes	Yes		Yes		0.5		1.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.985981	45.25753104	accessible	accessible	TRUE
448	Asphalt		Yes	Yes	Yes	Yes		Yes		0		2.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.98573516	45.25605449	accessible	NOT	FALSE
449	Asphalt		Yes	Yes	Yes	Yes		Yes		1		0.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.98560658	45.25457793	accessible	accessible	TRUE
450	Boardwalk		Yes	Yes	Yes	Yes		Yes		0.2		2.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	Asphalt crushed	-92.98533945	45.25261221	accessible	NOT	FALSE
451	Asphalt		Yes	Yes	Yes	Yes		Yes		0.2		2.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.98519864	45.2507539	accessible	NOT	FALSE
452	Asphalt		Yes	Yes	Yes	Yes		Yes		1.3		2.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.98479832	45.24815186	accessible	NOT	FALSE
453	Asphalt		Yes	Yes	Yes	Yes		Yes		0.5		0.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	Grass growing in cracks	-92.98464141	45.24643973	accessible	accessible	TRUE
454	Asphalt		Yes	Yes	Yes	Yes		Yes		0.2		1.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.98447176	45.24482898	accessible	accessible	TRUE
455	Asphalt		Yes	Yes	Yes	Yes		Yes		0.1		2.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.98433295	45.24342987	accessible	NOT	FALSE
456	Asphalt		Yes	Yes	Yes	Yes		Yes		0.2		1.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.98419951	45.24236843	accessible	accessible	TRUE
457	Asphalt		Yes	Yes	Yes	Yes		Yes		0.7		1.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.98400916	45.24088848	accessible	accessible	TRUE
458	Asphalt		Yes	Yes	Yes	Yes		Yes		0.1		1.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	Grass growing in cracks	-92.98387614	45.2395076	accessible	accessible	TRUE
459	Asphalt		Yes	Yes	Yes	Yes		Yes		0.5		1.4	Yes	Yes	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.98365385	45.23789555	accessible	accessible	TRUE
460	Asphalt		Yes	Yes	Yes	Yes		Yes		3.1		0.9	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.98354086	45.23670189	accessible	accessible	TRUE
461	Asphalt		Yes	Yes	Yes	Yes		Yes		0.2		1.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.98340147	45.2356609	accessible	accessible	TRUE
462	Asphalt		Yes	Yes	Yes	Yes		Yes		0.2		1.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.98331967	45.2348152	accessible	accessible	TRUE
463	Asphalt		Yes	Yes	Yes	Yes		Yes		1.4		2.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.98319754	45.233896	accessible	NOT	FALSE
464	Asphalt		Yes	Yes	Yes	Yes		Yes		0.5		0.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.98303636	45.23263968	accessible	accessible	TRUE
465	Asphalt		Yes	Yes	Yes	Yes		Yes		0.6		1.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.982932	45.23143269	accessible	accessible	TRUE
466	Asphalt		Yes	Yes	Yes	Yes		Yes		0.4		1.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.98276101	45.2301205	accessible	accessible	TRUE
467	Asphalt		Yes	Yes	Yes	Yes		Yes		0.5		1.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	Grass in cracks	-92.98265062	45.2286802	accessible	accessible	TRUE
468	Asphalt		Yes	Yes	Yes	Yes		Yes		0.8		0.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	Grass in cracks	-92.98245373	45.22729299	accessible	accessible	TRUE
469	Asphalt		Yes	Yes	Yes	Yes		Yes		0.7		1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.98230495	45.22584183	accessible	accessible	TRUE
470	Asphalt		Yes	Yes	Yes	Yes		Yes		0.5		1.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.98208401	45.22407706	accessible	accessible	TRUE
471	Asphalt		Yes	Yes	Yes	Yes		Yes		0.2		0.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.98196389	45.22290196	accessible	accessible	TRUE
472	Asphalt		Yes	Yes	Yes	Yes		Yes		0.8		0.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.98182333	45.22153534	accessible	accessible	TRUE
473	Asphalt		Yes	Yes	Yes	Yes		Yes		0.4		0.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.98163105	45.22013627	accessible	accessible	TRUE
475	Asphalt		Yes	Yes	Yes	Yes		Yes		0	0.4	0.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	Grass on trail	-92.98121346	45.21675694	accessible	accessible	TRUE
476	Asphalt		Yes	Yes	Yes	Yes	0	Yes		0.2		0.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.98101582	45.21519677	accessible	accessible	TRUE
477	Asphalt		Yes	Yes	Yes	Yes	0	Yes		0.5		2.5	Yes	No		No	N/A	N/A	N/A	N/A	N/A		-92.98077777	45.21269993	accessible	NOT	FALSE
478	Asphalt		Yes	Yes	Yes	Yes		Yes		0.2		0.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.9805909	45.21148078	accessible	accessible	TRUE
479	Asphalt		Yes	Yes	Yes	Yes		Yes		0.7		0.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.98095069	45.21388714	accessible	accessible	TRUE
481	Asphalt		Yes	Yes	Yes	Yes		Yes		2.5		2.6	Yes	No		No	N/A	N/A	N/A	N/A	N/A	Grass growing in cracks	-92.98039625	45.20992963	accessible	NOT	FALSE
482	Asphalt		Yes	Yes	Yes	Yes	0	Yes		0.8		0.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.98021937	45.20829813	accessible	accessible	TRUE
483	Asphalt		Yes	Yes	Yes	Yes	0	Yes		0.8		3.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.98012629	45.20681805	accessible	NOT	FALSE
484	Asphalt		Yes	Yes	Yes	Yes		Yes		0.2		0.9	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.97993111	45.20510601	accessible	accessible	TRUE
485	Asphalt		Yes	Yes	Yes	Yes		Yes		0		0.9	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.97994637	45.20384214	accessible	accessible	TRUE
486	Asphalt		Yes	Yes	Yes	Yes		Yes		0.6		1.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.98017369	45.20232561	accessible	accessible	TRUE
487	Asphalt		Yes	Yes	Yes	Yes		Yes		0.3	0	2.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	Grass growing in cracks	-92.98054853	45.20098245	accessible	NOT	FALSE
488	Asphalt		Yes	Yes	Yes	Yes		Yes		0.1		1.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.98106208	45.19977449	accessible	accessible	TRUE
489	Asphalt		Yes	Yes	Yes	Yes		Yes		0.5		2.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.98165804	45.1983991	accessible	NOT	FALSE
490	Asphalt		Yes	Yes	Yes	Yes		Yes		1.6		2.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.98264056	45.19637844	accessible	NOT	FALSE
491	Asphalt		Yes	Yes	Yes	Yes	0	Yes		0.7		0.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.98282178	45.19598168	accessible	accessible	TRUE
492	Asphalt		Yes	Yes	Yes	Yes		Yes		0.2		2.3	Yes	No	N/A	N/A	N/A	N/A	N/A	N/A	N/A		-92.98332361	45.19467301	accessible	NOT	FALSE
493	Asphalt		Yes	Yes	Yes	Yes		Yes		0.1		2.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.98369752	45.19337755	accessible	NOT	FALSE
494	Asphalt		Yes	Yes	Yes	Yes		Yes		0.2		2.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.98408493	45.19203275	accessible	NOT	FALSE
495	Asphalt		Yes	Yes	Yes	Yes	0	Yes		0.3		1.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.98456798	45.19047712	accessible	accessible	TRUE
496	Asphalt		Yes	Yes	Yes	Yes		Yes		0.4		1.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	Grass growing in cracks	-92.98510954	45.18861005	accessible	accessible	TRUE
497	Asphalt		Yes	Yes	Yes	Yes		Yes		0.6		1.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.98549301	45.18724543	accessible	accessible	TRUE
498	Asphalt		Yes	Yes	Yes	Yes		Yes	0	0.5		1.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.9860603	45.18539894	accessible	accessible	TRUE
499	Asphalt		Yes	Yes	Yes	Yes		Yes		0.1		1.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	Grass growing on trail	-92.98652147	45.18375814	accessible	accessible	TRUE
501	Asphalt		Yes	Yes	Yes	Yes		Yes		0.2		1.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	Grass growing in cracks	-92.98733787	45.1810082	accessible	accessible	TRUE
502	Asphalt		Yes	Yes	Yes	Yes	0	Yes		0.2		2.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.98773886	45.17967385	accessible	NOT	FALSE
503	Asphalt		Yes	Yes	Yes	Yes	0	Yes		0.4		1.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.98816315	45.17819603	accessible	accessible	TRUE
504	Asphalt		Yes	Yes	Yes	Yes		Yes		0.2		1.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.98855014	45.17684055	accessible	accessible	TRUE

ORT Self Evaluation Results - Parks

OBJECTID	O2	O3	O4	O5	O6	O7	O8	O9	O10	O11	O12	O13	O14	O15	O16	O17	O18	O19	O20	O21	O22	Comment	x	y	Running Slope Assessed	Cross Slope Assessed	ADA Compliant
505	Asphalt		Yes	Yes	Yes	Yes	0	Yes			0.1	2.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.98891107	45.17567543	accessible	NOT	FALSE
506	Asphalt		Yes	Yes	Yes	Yes		Yes			0.5	1.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.98935992	45.17410835	accessible	accessible	TRUE
507	Asphalt		Yes	Yes	Yes	Yes		Yes			0.4	0.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.98978195	45.17279067	accessible	accessible	TRUE
508	Asphalt		Yes	Yes	Yes	Yes		Yes			0.1	1.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	Grass on trail	-92.99017615	45.17128319	accessible	accessible	TRUE
509	Asphalt		Yes	Yes	Yes	Yes	0	Yes			0.2	0.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.99059994	45.16988433	accessible	accessible	TRUE
510	Asphalt		Yes	Yes	Yes	Yes		Yes			0.1	1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	Grass growing in cracks	-92.99098257	45.16858166	accessible	accessible	TRUE
511	Asphalt		Yes	Yes	Yes	Yes		Yes			0.3	1.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.99139387	45.16717358	accessible	accessible	TRUE
512	Asphalt		Yes	Yes	Yes	Yes		Yes			0.2	0	1.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.99172554	45.16605099	accessible	accessible	TRUE
513	Asphalt		Yes	Yes	Yes	Yes	0	Yes			0.4	0	1.6	Yes	No	No	N/A	N/A	N/A	N/A	N/A		-92.99213123	45.1646697	accessible	accessible	TRUE
514	Asphalt		Yes	Yes	Yes	Yes		Yes			0	0	1.6	Yes	No	Yes	No	N/A	N/A	N/A	N/A		-92.99257807	45.16304009	accessible	accessible	TRUE
515	Asphalt		Yes	Yes	Yes	Yes		Yes			0.3	0	2	Yes	No	No	N/A	N/A	N/A	N/A	N/A		-92.9930586	45.16138588	accessible	accessible	TRUE
516	Asphalt		Yes	Yes	Yes	Yes		Yes	0	0.1	0	2.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.99332209	45.16042584	accessible	NOT	FALSE
517	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			1.6	3	Yes	No	N/A	Yes	No	No	No	No	No		-92.84675282	45.11656499	accessible	accessible	FALSE
518	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			4.4	2.3	Yes	No	N/A	Yes	No	No	No	No	No		-92.84575562	45.11666637	accessible	accessible	FALSE
519	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			0.4	6.3	Yes	No	N/A	Yes	No	No	No	No	No		-92.84450739	45.11771381	accessible	NOT	FALSE
520	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			3.3	4.7	Yes	No	N/A	Yes	No	No	No	No	No		-92.8448927	45.11833026	accessible	accessible	FALSE
521	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			7.2	80	5.4	Yes	No	N/A	Yes	No	No	No	No		-92.84375829	45.11819599	NOT	NOT	FALSE
522	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			3.6	3.6	Yes	No	N/A	Yes	No	No	No	No	No		-92.84290208	45.11895936	accessible	accessible	FALSE
523	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			2.4	0.4	Yes	No	N/A	Yes	No	No	No	No	No		-92.84188922	45.11993405	accessible	accessible	FALSE
524	N/A	Dirt	Yes	Yes	N/A	Yes		Yes			4.4	3	Yes	No	N/A	Yes	No	No	No	No	No		-92.84031325	45.12064383	accessible	accessible	FALSE
525	N/A	Dirt	Yes	Yes	Yes	Yes		Yes	12.7	100	2.2	Yes	No	N/A	Yes	No	No	No	No	No	No		-92.83901129	45.12133098	NOT	accessible	FALSE
526	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			1.2	9.9	Yes	No	N/A	Yes	No	No	No	No	No		-92.84301826	45.11843772	accessible	NOT	FALSE
527	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			1.9	4.4	Yes	No	N/A	Yes	No	No	No	No	No		-92.84404328	45.11736731	accessible	accessible	FALSE
528	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			1.1	4.2	Yes	No	N/A	Yes	No	No	No	No	No		-92.84486379	45.11674667	accessible	accessible	FALSE
529	Asphalt		Yes	Yes	Yes	Yes		Yes			1.3	0.9	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90263169	44.97623663	accessible	accessible	TRUE
530	N/A	Rocks	Yes	Yes	Yes	Yes		Yes			0.8	0.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.8695619	45.20278326	accessible	accessible	TRUE
531	N/A	Grass	Yes	Yes	Yes	Yes		Yes			1.6	2.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.86878741	45.20264843	accessible	accessible	TRUE
532	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			3.6	4.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.86802642	45.20239681	accessible	accessible	TRUE
533	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			0.8	3.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.8673728	45.20208144	accessible	accessible	TRUE
534	N/A	Grass	Yes	Yes	Yes	Yes		Yes			1.1	1.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.86660267	45.20167651	accessible	accessible	TRUE
535	N/A	Grass	Yes	Yes	Yes	Yes		Yes			7.6	50	2.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.86606279	45.20128717	NOT	accessible	FALSE
536	N/A	Grass	Yes	Yes	Yes	Yes		Yes			0.3	1.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.86531228	45.2005179	accessible	accessible	TRUE
537	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			0.2	3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.86656118	45.20143666	accessible	accessible	TRUE
538	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0		3.8	4.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.86740198	45.20188792	accessible	accessible	TRUE
539	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	5.4	50	1.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.86838022	45.20218102	NOT	accessible	FALSE
540	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0		2.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.86865976	45.20240741	accessible	accessible	TRUE
541	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			1.8	4.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.86843278	45.20164319	accessible	accessible	TRUE
542	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	9.8	25	9.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.86855163	45.20114346	accessible	NOT	FALSE
543	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	3.5		9	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.8687103	45.20044521	accessible	NOT	FALSE
544	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	0.2		1.9	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.86870418	45.19987851	accessible	accessible	TRUE
545	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	14.1	100	0.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.86853554	45.19928792	NOT	accessible	FALSE
546	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	3.3		8.5	No	Yes	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.86867602	45.19857257	accessible	NOT	FALSE
547	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	5		2.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.86954765	45.19860283	accessible	accessible	TRUE
548	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes			2.5	2.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.88907233	44.99322709	accessible	accessible	TRUE
549	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes			6	50	9	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.90539957	44.98524433	NOT	NOT	FALSE
550	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes			2.2	3.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90673053	44.98479946	accessible	accessible	TRUE
551	N/A	Dirt	Yes	N/A	Yes	Yes	0	Yes			4.2	1.9	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90810265	44.98354021	accessible	accessible	TRUE
552	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			1.7	3.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90858092	44.98333833	accessible	accessible	TRUE
553	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	5.5	100	1.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.90977207	44.98405523	NOT	accessible	FALSE
554	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes			3	9	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91071093	44.98492544	accessible	NOT	FALSE
555	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			1.5	4.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91170863	44.98583324	accessible	accessible	TRUE
556	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes			4.3	10	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91298661	44.98578857	accessible	NOT	FALSE
557	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes			3.6	8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91329568	44.98695978	accessible	NOT	FALSE
558	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			6.3	150	9.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.91340713	44.98795906	NOT	NOT	FALSE
559	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			1.3	3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90884067	44.98271149	accessible	accessible	TRUE
560	N/A																										

ORT Self Evaluation Results - Parks

OBJECTID	O2	O3	O4	O5	O6	O7	O8	O9	O10	O11	O12	O13	O14	O15	O16	O17	O18	O19	O20	O21	O22	Comment	x	y	Running Slope Assessed	Cross Slope Assessed	ADA Compliant
566	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes		12	75	4.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91527999	44.98308599	NOT	accessible	FALSE
567	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	3		1.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91574751	44.98452818	accessible	accessible	TRUE
568	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes		16.5	25	1.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91698805	44.98553166	accessible	accessible	TRUE
569	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes		1.8	0	4.5	Yes	No	N/A	N/A	N/A	N/A	N/A	N/A	N/A		-92.91872646	44.98634307	accessible	accessible	TRUE
570	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes		1.1		4.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.92087264	44.98681493	accessible	accessible	TRUE
575	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes		0.6		1.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91473284	44.97629845	accessible	accessible	TRUE
576	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes		1.7		0.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91468202	44.9752834	accessible	accessible	TRUE
577	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	0.9		1.9	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91456434	44.97374407	accessible	accessible	TRUE
578	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes		1.6		5.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91419017	44.97238062	accessible	NOT	FALSE
579	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	0.8		1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91312408	44.9712976	accessible	accessible	TRUE
580	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes		6.6		0.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91184802	44.97094388	accessible	accessible	TRUE
581	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes		0.1		0.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91019913	44.97057219	accessible	accessible	TRUE
582	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes		1.5		4.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90826735	44.9702126	accessible	accessible	TRUE
583	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes		7.1	100	3.9	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90658452	44.9707648	NOT	accessible	FALSE
584	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	4.5		1.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.9072829	44.97193362	accessible	accessible	TRUE
585	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	1.7		0.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90714225	44.97336944	accessible	accessible	TRUE
586	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes		8.3	25	0.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90665928	44.97443163	accessible	accessible	TRUE
587	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes		4.4		5.4	Yes	No	N/A	N/A	N/A	N/A	N/A	N/A	N/A		-92.90515733	44.97456109	accessible	NOT	FALSE
588	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	11.6	10	7.9	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90491761	44.97603589	accessible	NOT	FALSE
589	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	7.2	30	1.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90632761	44.97673599	NOT	accessible	FALSE
590	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes		1.5		3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.9075533	44.97750071	accessible	accessible	TRUE
591	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes		6	25	3.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90837305	44.9779903	accessible	accessible	TRUE
592	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes		19	25	3.9	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90752941	44.97820512	accessible	accessible	TRUE
593	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes		4.5		3.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90598831	44.97827675	accessible	accessible	TRUE
594	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes		0.5		1.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90657178	44.97951136	accessible	accessible	TRUE
595	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes		9.6	50	9.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90761675	44.98051425	NOT	NOT	FALSE
596	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	3.7		5.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90759102	44.98199123	accessible	NOT	FALSE
597	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes		6.7	15	2.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.9058718	44.98180461	accessible	accessible	TRUE
598	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes		2.8		2.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90513285	44.98089655	accessible	accessible	TRUE
599	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes		12.7	25	0.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90377792	44.98001964	accessible	accessible	TRUE
600	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes		1.8		4.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90355756	44.97903602	accessible	accessible	TRUE
601	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes		2.7		5.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90456775	44.97819813	accessible	NOT	FALSE
602	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes		0.6		0.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90658636	44.97778377	accessible	accessible	TRUE
603	N/A	Dirt	Yes	Yes	N/A	N/A	0	Yes		2.8		7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90528691	44.97708505	accessible	NOT	FALSE
604	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	9.6	50	4.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90463514	44.97641412	NOT	accessible	FALSE
605	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	5.4	75	4.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90561817	44.97378618	NOT	accessible	FALSE
606	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes		4.9		10	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.9043209	44.97318457	accessible	NOT	FALSE
607	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	2.9		2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90463723	44.97219031	accessible	accessible	TRUE
608	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	0.5		2.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90554726	44.97124362	accessible	accessible	TRUE
609	N/A	Grass	Yes	Yes	Yes	Yes	Yes	Yes		3.7		9.6	Yes	Yes	No	Yes	Yes	Yes	No	No	No		-92.90066396	44.80358607	accessible	NOT	FALSE
610	N/A	Grass	Yes	Yes	Yes	Yes	Yes	Yes		8.5	500	0.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90015174	44.80345875	NOT	accessible	FALSE
611	N/A	Grass	Yes	Yes	Yes	Yes	Yes	Yes		11.6	500	9.9	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89903242	44.80391904	NOT	NOT	FALSE
612	N/A	Grass	Yes	Yes	Yes	Yes	0	Yes		0.7		6.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89763994	44.80448356	accessible	NOT	FALSE
613	N/A	Grass	Yes	Yes	Yes	Yes	Yes	Yes		10.1	100	1.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89740994	44.80355648	NOT	accessible	FALSE
614	N/A	Sand	No	Yes	Yes	Yes	Yes	Yes		26.3	100	18.9	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A	Steep and washout sand	-92.89770951	44.80336185	NOT	NOT	FALSE
615	N/A	Grass	Yes	Yes	Yes	Yes	Yes	Yes		12	100	12.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89841719	44.80261255	NOT	NOT	FALSE
616	N/A	Grass	Yes	Yes	Yes	Yes	Yes	Yes		2.2		0.5	Yes	No	N/A	Yes	N/A	N/A	N/A	N/A	N/A		-92.89971823	44.80271917	accessible	accessible	TRUE
617	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes		18	75	7.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90100921	44.8023261	NOT	NOT	FALSE
618	N/A	Grass	Yes	Yes	Yes	Yes	Yes	Yes		5.8	300	3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90154993	44.80286589	NOT	accessible	FALSE
619	N/A	Dirt	Yes	N/A	Yes	Yes	0	Yes		7.9	25	1.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.92323559	44.97701188	accessible	accessible	TRUE
620	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes		9.7	50	1.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.92326258	44.97587236	NOT	accessible	FALSE
621	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes		5.4	50	3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.92331681	44.9745028	NOT	accessible	FALSE
622	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes		2.9		5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.92192717	44.97393396	accessible	accessible	TRUE
623	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes		6.3	200	1.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.92070802	44.97312615	NOT	accessible	FALSE
624	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes		16.8	75	12	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91961545	44.97238138	NOT	NOT	FALSE
625	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes		3.8		2.9	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91808256	44.97201169	accessible	accessible	TRUE
626	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes		1.7		4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91662126	44.97134973	accessible	accessible	TRUE
627	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes	0	3.5		1.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.915167	44.97081011	accessible	accessible	TRUE
628	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes		3.3		0.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91334343	44.97091119	accessible	accessible	TRUE
629	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes		16.5	200	1.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91175556	44.97019391	NOT	accessible	FALSE
630	N/A	Dirt	Yes	Yes	Yes	Yes	Yes	Yes		11	100	8.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.91061303	44.96958027	NOT	NOT	FALSE

ORT Self Evaluation Results - Parks

OBJECTID	O2	O3	O4	O5	O6	O7	O8	O9	O10	O11	O12	O13	O14	O15	O16	O17	O18	O19	O20	O21	O22	Comment	x	y	Running Slope Assessed	Cross Slope Assessed	ADA Compliant
631	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			16	75	4	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.90937552	44.96918615	NOT	accessible	FALSE
632	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			4.6		2.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.90809569	44.96935182	accessible	accessible	TRUE
633	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			25	20	2	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.90701509	44.96981115	accessible	accessible	TRUE
634	N/A	Dirt	Yes	Yes	Yes	Yes		0	Yes		0.8		0.9	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.9040671	44.98104604	accessible	accessible	TRUE
635	N/A	Dirt	Yes	Yes	Yes	Yes		0	Yes		3		0.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.90517862	44.98157339	accessible	accessible	TRUE
636	N/A	Dirt	Yes	Yes	Yes	Yes		0	Yes		3.9		0.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.90445551	44.98214885	accessible	accessible	TRUE
637	N/A	Dirt	Yes	Yes	Yes	Yes		0	Yes	0	3.2		2	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.90325648	44.98212077	accessible	accessible	TRUE
638	N/A	Dirt	Yes	Yes	Yes	Yes		0	Yes		0.6		1.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.90207229	44.98180352	accessible	accessible	TRUE
639	N/A	Dirt	Yes	Yes	Yes	Yes		0	Yes		7	25	9	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.9008803	44.98186684	accessible	NOT	FALSE
640	N/A	Dirt	Yes	Yes	Yes	Yes		0	Yes		4.3		2.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.90077854	44.98273315	accessible	accessible	TRUE
641	N/A	Dirt	Yes	Yes	Yes	Yes		0	Yes		1.6		6	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.90114106	44.98356279	accessible	NOT	FALSE
642	N/A	Dirt	Yes	Yes	Yes	Yes		0	Yes		2.6		2.9	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.90181287	44.98438108	accessible	accessible	TRUE
644	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			0.2	0	0.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.90101784	44.97764618	accessible	accessible	TRUE
645	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			1.3		2.9	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.89943794	44.97768234	accessible	accessible	TRUE
646	N/A	Dirt	Yes	Yes	Yes	Yes		0	Yes		4.1	0	0.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.89747221	44.97703447	accessible	accessible	TRUE
647	N/A	Dirt	Yes	Yes	Yes	Yes		0	Yes		0.6	0	1.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.89565552	44.97717989	accessible	accessible	TRUE
648	N/A	Dirt	Yes	Yes	Yes	Yes		0	Yes		2.2	0	2.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.89487978	44.97801259	accessible	accessible	TRUE
649	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			13	40	3	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.89475656	44.97939649	NOT	accessible	FALSE
650	N/A	Dirt	Yes	Yes	Yes	Yes		0	Yes		3.3		5.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.89384821	44.98018564	accessible	NOT	FALSE
651	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			1.5		6.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.89374897	44.98108804	accessible	NOT	FALSE
652	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			3.3	0	1.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.89417452	44.98208909	accessible	accessible	TRUE
653	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			3.7		1.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.89557774	44.98260302	accessible	accessible	TRUE
654	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			0.8	0	1.9	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.89587756	44.98350115	accessible	accessible	TRUE
655	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			2.2		0.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.89713078	44.98279407	accessible	accessible	TRUE
656	N/A	Dirt	Yes	Yes	Yes	Yes		Yes	0		0.3		1.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.89802332	44.98246808	accessible	accessible	TRUE
657	N/A	Dirt	Yes	Yes	Yes	Yes		0	Yes		10.5	40	3	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.89960038	44.98280306	NOT	accessible	FALSE
658	N/A	Dirt	Yes	Yes	Yes	Yes		0	Yes		5	0	2.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.89984664	44.9815762	accessible	accessible	TRUE
659	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			0.5		0.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.89983004	44.98056434	accessible	accessible	TRUE
660	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			7.8	45	1.9	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.90011419	44.97939519	NOT	accessible	FALSE
661	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			1.4		6	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.89941765	44.97831933	accessible	NOT	FALSE
662	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			1	0	2.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.89984597	44.97775191	accessible	accessible	TRUE
663	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			0.6		1.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.90098524	44.97771453	accessible	accessible	TRUE
664	N/A	Dirt	Yes	Yes	Yes	Yes		0	Yes		5.5		1.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.89840864	44.97686691	accessible	accessible	TRUE
665	N/A	Dirt	Yes	Yes	Yes	Yes		0	Yes		2.9		0.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.89851685	44.97556177	accessible	accessible	TRUE
666	N/A	Dirt	Yes	Yes	Yes	Yes		0	Yes	0	2.8	0	4	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.89774245	44.97504971	accessible	accessible	TRUE
667	N/A	Dirt	Yes	Yes	Yes	Yes		0	Yes		1.5		5.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.89619481	44.97456947	accessible	NOT	FALSE
668	N/A	Dirt	Yes	Yes	Yes	Yes		0	Yes		4.9		7.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.89442078	44.97454831	accessible	NOT	FALSE
669		Dirt	Yes	Yes	Yes	Yes		0	Yes		9.4	50	6	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.89417779	44.97544119	NOT	NOT	FALSE
670	N/A	Dirt	Yes	Yes	Yes	Yes		0	Yes		0.1		3	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.89380253	44.9765318	accessible	accessible	TRUE
671	N/A	Dirt	Yes	Yes	Yes	Yes		0	Yes	0	3.8		3.5	Yes	No	N/A	N/A	N/A	N/A	N/A	N/A		-92.89415114	44.97747309	accessible	accessible	TRUE
672	N/A	Dirt	Yes	Yes	Yes	Yes		0	Yes		5.4	25	0.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.8938395	44.97401061	accessible	accessible	TRUE
673	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			6.6	75	5	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.89331689	44.97300424	NOT	accessible	FALSE
674	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			0.6		1.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.89223872	44.97288119	accessible	accessible	TRUE
675	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			7	25	0.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.89061942	44.97295009	accessible	accessible	TRUE
676	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			2.1		2.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.88915711	44.97284519	accessible	accessible	TRUE
677	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			9.2	30	1	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.88774627	44.97280119	NOT	accessible	FALSE
678	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			15.3	75	0.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.88612429	44.97295206	NOT	accessible	FALSE
679	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			25.3	25	0.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.88529021	44.97366222	accessible	accessible	TRUE
680	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			7	15	1.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.88688906	44.97397063	accessible	accessible	TRUE
681	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			7.2	10	0.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.88839134	44.97364155	accessible	accessible	TRUE
682	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			1.8		2.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.89016428	44.97324828	accessible	accessible	TRUE
683	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			0.4		5	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.89196606	44.97334199	accessible	accessible	TRUE
684	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			5.6	20	8.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.89322334	44.97351939	accessible	NOT	FALSE
685	N/A	Dirt	Yes	Yes	Yes	Yes		0	Yes		2.6		7	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.89490651	44.97364223	accessible	NOT	FALSE
686	N/A	Dirt	Yes	Yes	Yes	Yes		0	Yes		1.6		0.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.89615944	44.97390781	accessible	accessible	TRUE
687	N/A	Dirt	Yes	Yes	Yes	Yes		0	Yes		2.9		3.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.89766894	44.97425406	accessible	accessible	TRUE
688	N/A	Dirt	Yes	Yes	Yes	Yes		0	Yes		2.4		0.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.89890443	44.97451327	accessible	accessible	TRUE
690	N/A	Dirt	Yes	Yes	Yes	Yes		0	Yes		7.1	200	3.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.90096512	44.97579474	NOT	accessible	FALSE
691	N/A	Dirt	Yes	Yes	Yes	Yes		0	Yes		17.5	50	0.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.90133895	44.97682819	NOT	accessible	FALSE
692	N/A	Dirt	Yes	Yes	Yes	Yes		Yes			1.2		4	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.90204496	44.97633684	accessible	accessible	TRUE
693	N/A	Dirt	Yes	Yes	Yes	Yes		0	Yes	0	4.5		0.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A		-92.90214169	44.97557664	accessible	accessible	TRUE

ORT Self Evaluation Results - Parks

OBJECTID	O2	O3	O4	O5	O6	O7	O8	O9	O10	O11	O12	O13	O14	O15	O16	O17	O18	O19	O20	O21	O22	Comment	x	y	Running Slope Assessed	Cross Slope Assessed	ADA Compliant
694	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes		21.1	100	2.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90133309	44.97489193	NOT	accessible	FALSE
696	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes		8.2	25	5.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.8996148	44.97390927	accessible	NOT	FALSE
697	N/A	Dirt	Yes	Yes	Yes	Yes		Yes		5.8	20	3.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89990305	44.97312254	accessible	accessible	TRUE
698	N/A	Dirt	Yes	Yes	Yes	Yes		Yes		3		0.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89877602	44.97240355	accessible	accessible	TRUE
699	N/A	Dirt	Yes	Yes	Yes	Yes		Yes		2.3		5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89871181	44.97145623	accessible	accessible	TRUE
700	N/A	Dirt	Yes	Yes	Yes	Yes		Yes		1.6		4.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89777832	44.97108013	accessible	accessible	TRUE
701	N/A	Dirt	Yes	Yes	Yes	Yes		Yes		2.8		3.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89638307	44.97151138	accessible	accessible	TRUE
702	N/A	Dirt	Yes	Yes	Yes	Yes		Yes		17.5	100	1.3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.8949273	44.97164779	NOT	accessible	FALSE
703	N/A	Dirt	Yes	Yes	Yes	Yes		Yes		0.2		1.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89376875	44.97215549	accessible	accessible	TRUE
704	N/A	Dirt	Yes	Yes	Yes	Yes		Yes		1.4		0.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89494406	44.97100758	accessible	accessible	TRUE
705	N/A	Dirt	Yes	Yes	Yes	Yes		Yes		0.6		4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89634611	44.9708969	accessible	accessible	TRUE
706	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes		4		8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89625969	44.9697907	accessible	NOT	FALSE
707	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes		3.5		4.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89592559	44.96857687	accessible	accessible	TRUE
708	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes		1.7		3.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89676579	44.96772997	accessible	accessible	TRUE
709	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes		2.5		3.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89821569	44.96756664	accessible	accessible	TRUE
710	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes		2.7		2.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89969292	44.96730517	accessible	accessible	TRUE
711	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes		2.9		1.9	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90139386	44.96728765	accessible	accessible	TRUE
712	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes		16.9	50	12.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.9021675	44.96789425	NOT	NOT	FALSE
713	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes		7.3	75	3.6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90231167	44.969081	NOT	accessible	FALSE
714	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes		4		1.7	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90140636	44.96922806	accessible	accessible	TRUE
715	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes		4.6		5.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89999316	44.96868035	accessible	NOT	FALSE
716	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes		3.6		1.8	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.89937558	44.96955005	accessible	accessible	TRUE
717	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes		4.6		4.1	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90029784	44.97028816	accessible	accessible	TRUE
718	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes		4.4		6	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90106755	44.97090298	accessible	NOT	FALSE
719	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes		1.6		1.2	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90248945	44.97070236	accessible	accessible	TRUE
720	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes		1.8		1.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90247772	44.96973831	accessible	accessible	TRUE
721	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes		15	50	5.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90194664	44.97180068	NOT	NOT	FALSE
722	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes		5		2.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.9027192	44.97244047	accessible	accessible	TRUE
723	N/A	Dirt	Yes	Yes	Yes	Yes		Yes		2.9		1.4	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90190817	44.97279381	accessible	accessible	TRUE
724	N/A	Dirt	Yes	Yes	Yes	Yes		Yes		1.9		0.5	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90072531	44.97286271	accessible	accessible	TRUE
725	N/A	Dirt	Yes	Yes	Yes	Yes	0	Yes		2.5		3	Yes	No	N/A	No	N/A	N/A	N/A	N/A	N/A		-92.90302841	44.97300206	accessible	accessible	TRUE

Picnic Area Self Evaluation Results - Parks

OBJECTID	P1	P2	P3	P4	P5	P6	P7	P8	Comment	x	y	ADA Compliant
1	3	Yes	Yes	Yes	Yes	N/A	Yes	3		-92.83785869	45.12057472	TRUE
2	20	Yes	Yes	Yes	Yes	No	Yes	0	Picnic tables are moveabe	-92.79510101	45.15361744	FALSE
3	9	Yes	Yes	Yes	Yes	No	Yes	4		-92.8717904	45.20412964	FALSE
4	6	Yes	Yes	Yes	Yes	No	Yes	2		-92.87200562	45.20256089	FALSE
5	8	Yes	Yes	Yes	Yes	No	Yes	4		-92.87044929	45.20320168	FALSE
6	7	Yes	Yes	Yes	Yes	No	Yes	0		-92.87118754	45.20294359	FALSE
7	14	Yes	Yes	Yes	Yes	Yes	Yes	0	The grill by concrete pad nearest to boat launch is accessible	-92.87116611	45.20345406	TRUE
8	8	Yes	Yes	Yes	Yes	No	Yes	8	Parking spot is poorly marked	-92.79243182	44.80029423	FALSE
9	8	Yes	Yes	No	N/A	Yes	Yes	8		-92.79608486	44.79928665	FALSE
10	17	Yes	Yes	Yes	Yes	Yes	Yes	17		-92.79527061	44.80085251	TRUE
11	8	Yes	Yes	Yes	Yes	No	Yes	1		-92.90014622	44.80665962	FALSE
12	38	Yes	Yes	Yes	Yes	Yes	Yes	2		-92.89234864	44.99046673	TRUE
13	26	Yes	Yes	Yes	Yes	Yes	Yes	2	Tables need to be moved to a more accessible location	-92.89050434	44.98690218	TRUE
14	134	Yes	Yes	Yes	Yes	Yes	Yes	0	All tables around swimming area	-92.8919489	44.9848311	TRUE
15	4	Yes	Yes	Yes	Yes	No	Yes	0		-92.89622954	44.98136126	FALSE
16	6	Yes	Yes	Yes	Yes	No	Yes	0		-92.90194212	44.97745788	FALSE
17	34	Yes	Yes	Yes	Yes	No	No	0	2 round concrete tables are missing one bench so potential accessible tables	-92.80909112	44.7494079	FALSE
18	4	Yes	Yes	Yes	Yes	No	Yes	0		-92.80275143	45.03686864	FALSE
19	10	Yes	Yes	Yes	Yes	No	Yes	0		-92.81355486	44.75011828	FALSE
20	9	Yes	Yes	Yes	Yes	No	Yes	0	Mole tunnels are causing some stabilization issues	-92.87274946	45.20602894	FALSE
21	5	Yes	Yes	Yes	Yes	No	Yes	0		-92.79115113	44.80165215	FALSE
22	3	Yes	Yes	Yes	No	No	Yes	0		-92.89724606	44.98562845	FALSE
23	6	Yes	Yes	Yes	Yes	No	Yes	0		-92.89559512	44.98548851	FALSE
24	8	Yes	Yes	Yes	Yes	No	Yes	0		-92.89725937	44.99071952	FALSE
25	3	Yes	Yes	Yes	Yes	No	Yes	0		-92.89585075	44.98920262	FALSE
26	9	Yes	Yes	Yes	Yes	Yes	Yes	0		-92.89387357	44.98792329	TRUE
27	4	No	Yes	No	No	No	No	0		-92.90031116	44.80578871	FALSE
28	32	Yes	Yes	No	Yes	Yes	Yes	0		-92.79459143	45.15444417	FALSE
31	2	Yes	Yes	No	Yes	No	Yes	0		-92.90479029	44.97493995	FALSE

Picnic Area Self Evaluation Results - Parks

32	2	Yes	Yes	Yes	Yes	No	Yes	0	Grass growing on cement pad. Tables dilapidated. Overgrown vegetation.	-92.9148826	44.97322996	FALSE
----	---	-----	-----	-----	-----	----	-----	---	---	-------------	-------------	-------

Play Area Self Evaluation Results - Parks

OBJECTID	P1	P2	P3	P4	P5	P6	P7	P8	B1	P9	P10	P11	P12	P13	P14	P15	P16	P17	P18	P19	P20	P21	P22	B2	P23	P24	P25	P26	P27	P28	P29	P30	P31	P32	P33	P34	P35	P36	P37	P38	P39	B3
9	Yes	Yes	Yes	Yes	Yes	Yes	N/A	N/A	Zero	Yes	Yes	Yes	Yes	Yes	No	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Yes	Zero	Yes	N/A	No	N/A	N/A	No	N/A	N/A	N/A	Yes	Yes	No	No	No	No	No	Zero	
10	No	Yes	Yes	Yes	Yes	N/A	N/A	N/A	Zero	Yes	No	Yes	Yes	Yes	N/A	N/A	N/A	N/A	Yes	Yes	Yes	N/A	N/A	Zero	N/A	N/A	No	N/A	N/A	N/A	Yes	N/A	N/A	N/A	Yes	Yes	Yes	Yes	No	N/A	N/A	Zero
11	Yes	Yes	Yes	Yes	Yes	N/A	Yes	No	Zero	Yes	Yes	Yes	Yes	Yes	N/A	N/A	N/A	N/A	Yes	N/A	Yes	N/A	Yes	Zero	N/A	Yes	N/A	N/A	N/A	Yes	No	Yes	N/A	N/A	Yes	No	Yes	Yes	No	N/A	N/A	Zero
12	Yes	No	Yes	Yes	Yes	Yes	Yes	N/A	Zero	Yes	Yes	Yes	N/A	Yes	N/A	N/A	N/A	N/A	No	N/A	Yes	N/A	No	Zero	No	N/A	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	No	Yes	No	Zero
13	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	0	Yes	N/A	Yes	Yes	Yes	N/A	N/A	N/A	N/A	Yes	N/A	N/A	Yes	Yes	0	Yes	Yes	No	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	0
14	Yes	Yes	Yes	Yes	Yes	Yes	Yes	No	Zero	Yes	N/A	Yes	Yes	Yes	N/A	N/A	N/A	Circular	N/A	Yes	N/A	Yes	Yes	Zero	N/A	Yes	N/A	N/A	N/A	Yes	N/A	Yes	N/A	Yes	Yes	Yes	Yes	Yes	N/A	No	No	Zero
15	No	Yes	Yes	Yes	Yes	No	No	N/A	Zero	Yes	Yes	Yes	No	Yes	N/A	N/A	N/A	Circular	N/A	N/A	No	No	Yes	Zero	N/A	N/A	N/A	N/A	N/A	Yes	No	Yes	Yes	N/A	Yes	Yes	Yes	No	No	No	Zero	
27	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Zero	Yes	N/A	Yes	Yes	Yes	N/A	N/A	N/A	Circular	N/A	N/A																						

Play Area Self Evaluation Results - Parks

OBJECTID	P40	P41	P42	P43	P44	B4	P45	P46	P47	P48	P49	B5	P50	P51	P52	P53	P54	P55	P56	P57	B6	P58	P59	Comment	x	y	ADA Compliant				
9	Yes	Yes	Yes	Yes	N/A	Zero	No	No	N/A	N/A	N/A	Zero	No	No	No	No	N/A	N/A	N/A	N/A	Zero	Sand	Yes	Difficulty going over lip at accessible point	-92.79487772	44.80131319	FALSE				
10	Yes	No	N/A	N/A	N/A	Zero	N/A	N/A	N/A	N/A	N/A	Zero	No	N/A	N/A	N/A	N/A	N/A	N/A	Yes	Zero	Sand	Yes	Tripping hazard to entrance of play ground	-92.78899019	44.80392151	FALSE				
11	Yes	Yes	Yes	N/A	N/A	Zero	N/A	N/A	N/A	N/A	N/A	Zero	No	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Zero	Sand	Yes	Rout needs updating	-92.90014302	44.8057161	FALSE				
12	Yes	Yes	Yes	N/A	N/A	Zero	N/A	N/A	N/A	N/A	N/A	Zero	No	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Zero	Sand	Yes	Access routs need to be put in for the younger child play structure	-92.89187922	44.99084382	FALSE				
13	Yes	Yes	Yes	Yes	Yes	0	N/A	N/A	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	Sand	Yes		-92.89099527	44.98646909	FALSE				
14	Yes	Yes	Yes	Yes	N/A	Zero	N/A	N/A	N/A	N/A	N/A	Zero	No	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Zero	Sand	Yes		-92.88967738	44.98290394	FALSE				
15	Yes	Yes	N/A	N/A	N/A	Zero	N/A	N/A	N/A	N/A	N/A	Zero	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Zero	Sand	Yes		-92.89620044	44.98117852	FALSE				
27																													-92.87246399	45.20301513	TRUE

Archery Range Self Evaluation Results - Parks

OBJECTID	S1	S2	S3	Comment	x	y	ADA Compliant
1	Yes	Yes	Yes	Route questionable	-92.90058558	44.98764517	TRUE

Viewing Facility Self Evaluation Results - Parks

OBJECTID	V1	V2	Comment	x	y	ADA Compliant
1	Yes	Yes		-92.78825553	44.79977057	TRUE
2	Yes	No		-92.91220598	44.98085311	FALSE
3	Yes	No	Boardwalk flooded. Cannot reach viewing facility	-92.90982571	44.97774249	FALSE

Exterior Water Fountain Self Evaluation Results - Parks

OBJECTID	W1	W2	W3	W4	W5	W6	W7	W8	W9	W10	W11	Comment	x	y	ADA Compliant
1	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	N/A		-92.83781268	45.12054774	TRUE
2	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	N/A	N/A		-92.79508081	45.15380692	TRUE
3	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Yes	N/A	N/A			-92.87193012	45.20427126	TRUE
4	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	N/A	N/A		-92.87202409	45.20276691	TRUE
5	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	N/A	N/A		-92.88096691	45.2021029	TRUE
6	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Yes	N/A	N/A	N/A		-92.80951671	44.74936903	TRUE
7	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Yes	N/A	N/A	N/A		-92.81257452	44.74977458	TRUE
8	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	N/A	Yes	No water flows out of the fountain when the button is pressed	-92.79238648	44.80044129	TRUE
9	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	N/A	N/A	Fountain leaks	-92.79605753	44.79924397	TRUE
10	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	N/A	N/A	N/A		-92.79579819	44.80234903	TRUE
11	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	N/A	N/A		-92.79402654	44.80129064	TRUE
12	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	N/A	N/A		-92.78938833	44.8033655	TRUE
13	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	N/A	N/A		-92.78905934	44.80394972	TRUE
14	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes		-92.79049516	44.80322171	TRUE
15	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	N/A	N/A	Weak stream	-92.80393671	44.80130925	TRUE
16	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	N/A	N/A	N/A		-92.90023598	44.8065616	TRUE
17	Yes	No	N/A	N/A	Yes	Yes	No	Yes	N/A	N/A	N/A	Fountain does not work	-92.90020119	44.80596095	FALSE
18	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Yes	N/A	N/A	N/A		-92.89196916	44.9904559	TRUE
19	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	N/A	N/A	Fountain leaks	-92.89090851	44.98695935	TRUE
20	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	N/A	N/A		-92.88973907	44.98299324	TRUE
21	Yes	No	Yes	N/A	Yes	Yes	No	Yes	N/A	N/A	N/A		-92.89185751	44.98465588	FALSE
22	Yes	No	N/A	N/A	Yes	Yes	No	Yes	N/A	N/A	N/A		-92.89776013	44.98055365	FALSE
23	Yes	N/A	N/A	N/A	Yes	Yes	No	Yes	N/A	N/A	N/A		-92.89719789	44.98093687	FALSE
24	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Yes	N/A	N/A	N/A	Weak stream on side spout	-92.89807088	44.9814398	TRUE
25	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Yes	N/A	N/A	N/A		-92.8964236	44.98139002	TRUE
26	Yes	N/A	N/A	N/A	Yes	Yes	No	Yes	N/A	N/A	N/A		-92.89537689	44.9807884	FALSE
27	Yes	N/A	N/A	N/A	Yes	Yes	No	Yes	N/A	N/A	N/A		-92.89419928	44.98144541	FALSE
28	Yes	N/A	N/A	N/A	Yes	Yes	No	Yes	N/A	N/A	N/A		-92.89526951	44.98211139	FALSE
29	Yes	N/A	N/A	N/A	Yes	Yes	No	Yes	N/A	N/A	N/A		-92.89604125	44.98232795	FALSE
30	Yes	N/A	N/A	N/A	Yes	Yes	No	Yes	N/A	N/A	N/A		-92.89706986	44.98213902	FALSE
31	Yes	N/A	N/A	N/A	Yes	Yes	No	Yes	N/A	N/A	N/A		-92.89848035	44.98222062	FALSE
32	Yes	N/A	N/A	N/A	Yes	Yes	No	Yes	N/A	N/A	N/A		-92.89926984	44.98209999	FALSE
33	No	Yes	N/A	Yes	Yes	Yes	Yes	Yes	N/A	N/A	N/A		-92.90464504	44.97596032	FALSE
34	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Yes	N/A	N/A	N/A		-92.90220925	44.97741723	TRUE
35	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Yes	N/A	N/A	N/A		-92.90324408	44.97093889	TRUE

Facility: **Big Marine Contact Station**

Access to Goods and Services

Interior Accessible Route – **YES, all standards met**

Signs – **YES except door signs are hung too high**

Interior Doors – **YES, all standards met**

Sales and Service Counters – **YES except counter is not long enough**

Toilet Rooms

Accessible Route – **YES, all standards met**

Signs at Toilet Rooms – **YES, all standards met**

Entrance – **YES, all standards met**

In the Toilet Room – **YES, all standards met**

Lavatories – **YES, all standards met**

Soap Dispensers and Hand Dryers – **YES, all standards met**

Water Closets in Single-User Toilet Rooms and Compartments (Stalls) – **YES except TP dispenser is too far away from toilet**

Additional Access

Drinking Fountains – **YES, all standards met**

Fire Alarm Systems – **YES, all standards met**

General Summary of the Facility

No. of Accessible Entrances: 1

No. of Accessible Toilet Rooms: 0

No. of Accessible Drinking Fountains: 1

No. of Accessible Floors: 1

No. of Barriers Identified for Correction: 3

Services Provided at this Facility

Restrooms, Drinking fountains, Service Counter

Facility: **Big Marine Park Restrooms**

Toilet Rooms

Accessible Route – **YES, all standards met**

Signs at Toilet Rooms – **YES, all standards met**

Entrance – **YES, all standards met**

In the Toilet Room – **YES except coat hook are too high**

Lavatories – **YES, all standards met**

Soap Dispensers and Hand Dryers – **YES, all standards met**

Water Closets in Single-User Toilet Rooms and Compartments (Stalls) –

Women’s – YES except flush control is on closed side

Men’s – YES, all standards met

Toilet Compartments (Stalls) – **YES except there is not a door pull on both sides of doors**

General Summary of the Facility

No. of Accessible Entrances: N/A

No. of Accessible Toilet Rooms: 0

No. of Accessible Drinking Fountains: N/A

No. of Accessible Floors: N/A

No. of Barriers Identified for Correction: 3

Services Provided at this Facility

Restrooms

Facility: **Big Marine Swim Restrooms**

Toilet Rooms

Accessible Route – **YES, all standards met**

Signs at Toilet Rooms – **YES, all standards met**

Entrance – **YES, all standards met**

In the Toilet Room –

Women's – YES except coat hook are too high

Men's – YES except coat hook are too high

Unisex – YES, all standards met

Lavatories – **YES, all standards met**

Soap Dispensers and Hand Dryers – **YES, all standards met**

Water Closets in Single-User Toilet Rooms and Compartments (Stalls) –

Women's – YES except toilet is hung too far from side wall

Men's – YES except side bar does not extend 54" from back wall

Unisex – YES, all standards met

Toilet Compartments (Stalls) –

Women's – YES except there is not a door pull on both sides of doors, not self-closing

Men's – YES except there is not a door pull on both sides of doors, not self-closing

Unisex – YES, all standards met

General Summary of the Facility

No. of Accessible Entrances: N/A

No. of Accessible Toilet Rooms: 1 (unisex)

No. of Accessible Drinking Fountains: N/A

No. of Accessible Floors: N/A

No. of Barriers Identified for Correction: 6

Services Provided at this Facility

Restrooms

Facility: Lake Elmo Campground (playground bathroom)

Toilet Rooms

Accessible Route- **Standards met**

Signs at Toilet Rooms- **text does not contrast with background, text is not raised, no braille, sign mounded on door**

Entrance- **Standards met**

In the Toilet Room- **m/w mirror is to high**

Lavatories- **m/w counted extends out to far, the pipes are not insulated or protected**

Soap Dispensers and Hand Dryers- **Standards met**

Water Closets in Single-User Toilet Rooms and Compartments (Stalls)- **Stalls are to narrow, m/w side grab bar is to short, does not extend far enough from rear wall, m/w grab bar is not mounted high enough, m/w toilet paper is mounted 0in from front of toilet**

Toilet Compartments (Stalls)- **Stalls are not wide enough**

Additional Access

Fire Alarm Systems- **Standards met**

General Summary of the Facility

No. of Accessible Entrances: 1

No. of Accessible Toilet Rooms: 2

No. of Accessible Floors: 1

No. of Barriers Identified for Correction: 4

Services Provided at this Facility

Bathrooms

Facility: **Lake Elmo North Shelter**

Toilet Rooms

Accessible Route **Yes it's compliant**

Signs at Toilet Rooms **No contrast, no raised letters, no braille, sign mounted on door, height is compliant**

Entrance **Yes it's compliant**

In the Toilet Room **Compliant except for Men's mirrors**

Lavatories **Compliant except for Men's counter surface height**

Soap Dispensers and Hand Dryers **All is compliant**

Water Closets in Single-User Toilet Rooms and Compartments (Stalls) **Compliant except for Men's water closet centerline, men and women's stall size, men and women's side hand rails, and the distance away from the toilet paper dispenser.**

Toilet Compartments (Stalls) **Compliant except for width of door and width of stall**

General Summary of the Facility

No. of Accessible Entrances: **1**

No. of Accessible Toilet Rooms: **1**

Services Provided at this Facility

Bathroom

Facility: **LAKE ELMO CAMPGROUND RESTROOMS (FRONT LOOP)**

Toilet Rooms

Accessible Route – **YES, all standards met**

Signs at Toilet Rooms – **YES except no contrasting colors, no raised text, no braille, on door**

Entrance – **YES, all standards met**

In the Toilet Room – **YES, all standards met**

Lavatories – **YES except pipes are not insulated**

Soap Dispensers and Hand Dryers – **YES except soap dispensers are too high**

Water Closets in Single-User Toilet Rooms and Compartments (Stalls) –

Women’s – YES except side bar is too short and positioned incorrectly, no back bar, TP dispenser is too close to toilet

Men’s – YES except toilet is located too far from side wall, side bar is too short and positioned incorrectly, no back bar, TP dispenser is too close to toilet

Toilet Compartments (Stalls) – **YES except door openings are too narrow, not self-closing, stalls too narrow**

General Summary of the Facility

No. of Accessible Entrances: N/A

No. of Accessible Toilet Rooms: 0

No. of Accessible Drinking Fountains: N/A

No. of Accessible Floors: N/A

No. of Barriers Identified for Correction: 18

Services Provided at this Facility

Restrooms

Facility: **Lake Elmo Contact Station**

Access to Goods and Services

Interior Accessible Route – **YES, all standards met**

Signs – **YES, all standards met**

Sales and Service Counters – **YES except counter is not long enough**

Toilet Rooms

Accessible Route – **YES, all standards met**

Signs at Toilet Rooms – **YES, all standards met**

Entrance – **YES except maneuvering clearance is not wide enough, door closes too fast**

In the Toilet Room – **YES except coat hooks are too high**

Lavatories – **YES except knee clearance on sink is not high enough**

Soap Dispensers and Hand Dryers – **YES except paper towel dispenser is too high**

Water Closets in Single-User Toilet Rooms and Compartments (Stalls) – **YES except side bar is too short and positioned incorrectly, back bar is too short and positioned incorrectly,**

Additional Access

Drinking Fountains – **YES, all standards met**

Public Telephones - **YES except operable parts are too high,**

Fire Alarm Systems – **YES, all standards met**

General Summary of the Facility

No. of Accessible Entrances: 1

No. of Accessible Toilet Rooms: 0

No. of Accessible Drinking Fountains: 1

No. of Accessible Floors: 1

No. of Barriers Identified for Correction: 9

Services Provided at this Facility

Restrooms, Drinking fountains, Service Counter, Pay phone

Facility: **Lake Elmo Nordic Center**

Access to Goods and Services

Interior Accessible Route – **YES, all standards met**

Signs – **YES, all standards met**

Interior Doors – **YES, all standards met**

Seating General – **YES, all standards met**

Benches – In locker rooms, dressing rooms, fitting rooms – **YES except there is not clear floor space, the bench seat is not deep enough, the bench does not have a back and is not affixed to a wall**

Toilet Rooms

Accessible Route – **YES, all standards met**

Signs at Toilet Rooms – **YES except signs are not on latch side**

Entrance – **YES, all standards met**

In the Toilet Room – **YES except Men's mirror is too high, coat hooks are too high**

Lavatories – **YES except pipes are not insulated**

Soap Dispensers and Hand Dryers – **YES, all standards met**

Water Closets in Single-User Toilet Rooms and Compartments (Stalls) – **YES except Men's side bar is too close to objects hung above it, TP dispensers are hung too close to toilet**

Toilet Compartments (Stalls) – **YES, all standards met**

Additional Access

Drinking Fountains – **YES, all standards met**

Fire Alarm Systems – **YES, all standards met**

General Summary of the Facility

No. of Accessible Entrances: 1

No. of Accessible Toilet Rooms: 0

No. of Accessible Drinking Fountains: 1

No. of Accessible Floors: 1

No. of Barriers Identified for Correction: 9

Services Provided at this Facility

Restrooms, Drinking fountains, Locker rooms

Facility: **LAKE ELMO PLAYGROUND RESTROOMS**

Toilet Rooms

Accessible Route – **YES, all standards met**

Signs at Toilet Rooms – **YES, all standards met**

Entrance – **YES, all standards met**

In the Toilet Room – **YES, all standards met**

Lavatories – **YES except pipes are not insulated**

Soap Dispensers and Hand Dryers – **YES, all standards met**

Water Closets in Single-User Toilet Rooms and Compartments (Stalls) –

Women’s – YES except toilet is located too far from side wall

Men’s – YES except toilet is located too far from side wall

Toilet Compartments (Stalls) – **YES except doors are not self-closing**

General Summary of the Facility

No. of Accessible Entrances: N/A

No. of Accessible Toilet Rooms: 0

No. of Accessible Drinking Fountains: N/A

No. of Accessible Floors: N/A

No. of Barriers Identified for Correction: 4

Services Provided at this Facility

Restrooms

Facility: **LAKE ELMO SOUTH SHELTER RESTROOMS**

Toilet Rooms

Accessible Route – **YES, all standards met**

Signs at Toilet Rooms –

Women’s – YES except not on latch side of door

Men’s – YES except no raised text, no braille, not on latch side of door, sign hung too high

Entrance – **YES except doors close too quickly**

In the Toilet Room – **YES, all standards met**

Lavatories – **YES except pipes are not insulated**

Soap Dispensers and Hand Dryers – **YES, all standards met**

Water Closets in Single-User Toilet Rooms and Compartments (Stalls) –

Women’s – YES except toilet is located too far from side wall, side bar is positioned incorrectly, side bar hung too low, TP dispenser is too close to toilet

Men’s – YES except toilet is located too far from side wall, side bar is positioned incorrectly, side bar hung too low, TP dispenser is too close to toilet

Toilet Compartments (Stalls) – **YES except doors are not self-closing**

General Summary of the Facility

No. of Accessible Entrances: N/A

No. of Accessible Toilet Rooms: 0

No. of Accessible Drinking Fountains: N/A

No. of Accessible Floors: N/A

No. of Barriers Identified for Correction: 17

Services Provided at this Facility

Restrooms

Facility: **LAKE ELMO SWIM BEACH RESTROOMS**

Toilet Rooms

Accessible Route – **YES, all standards met**

Signs at Toilet Rooms – **No, Painted on door. No braille or raised text. No handicap symbol. Label too high off ground.**

Entrance – **YES except handle is too high**

In the Toilet Room – **YES, all standards met**

Lavatories – **YES except pipes are not insulated**

Soap Dispensers and Hand Dryers – **YES, all standards met**

Water Closets in Single-User Toilet Rooms and Compartments (Stalls) –

Women’s – YES except toilet is located too far from side wall, toilet is hung too high, side bar is too short, side bar is positioned incorrectly, side bar hung too low, back bar too short, TP dispenser is hung too close to toilet

Men’s – YES except toilet is located too far from side wall, side bar is too short, side bar is positioned incorrectly, side bar hung too low, no back bar, TP dispenser is hung too close to toilet

Toilet Compartments (Stalls) – **YES except door openings are too narrow, compartments are not wide enough**

General Summary of the Facility

No. of Accessible Entrances: N/A

No. of Accessible Toilet Rooms: 0

No. of Accessible Drinking Fountains: N/A

No. of Accessible Floors: N/A

No. of Barriers Identified for Correction: 24

Services Provided at this Facility

Restrooms

Facility: **PINE POINT**

Toilet Rooms

Accessible Route – **YES, all standards met**

Signs at Toilet Rooms – **No, Painted on door. No braille or raised text. No handicap symbol**

Entrance – **YES except door closes in 3 seconds**

In the Toilet Room – **YES except coat hook are 63” high**

Lavatories – **YES except one sink in women’s bathroom is not insulated**

Soap Dispensers and Hand Dryers – **YES, all standards met**

Water Closets in Single-User Toilet Rooms and Compartments (Stalls) –

Women’s – YES except toilet is located too far from side wall, flush control located on closed side, TP dispenser is too high off the ground

Men’s – YES except toilet is located too far from side wall, side bar is non-compliant

Toilet Compartments (Stalls) – **YES except there is not a door pull on both sides of doors**

General Summary of the Facility

No. of Accessible Entrances: N/A

No. of Accessible Toilet Rooms: 0

No. of Accessible Drinking Fountains: N/A

No. of Accessible Floors: N/A

No. of Barriers Identified for Correction: 15

Services Provided at this Facility

Restrooms

Facility: **POINT DOUGLAS PINIC RESTROOMS**

Toilet Rooms

Accessible Route – **YES, all standards met**

Signs at Toilet Rooms – **YES except no raised text, no braille, sign not mounted on latch side, sign too high**

Entrance – **YES except threshold is too high, handles too low, closes too quickly**

In the Toilet Room – **YES, all standards met**

Lavatories – **YES except sinks extend too far out, pipes are not insulated**

Soap Dispensers and Hand Dryers – **YES except soaps are too high**

Water Closets in Single-User Toilet Rooms and Compartments (Stalls) –

Women’s – toilet is too close to side wall, side bar is too short and positioned incorrectly, no back bar, TP is too far away from toilet, door opening is too narrow, stall too narrow

Men’s – toilet is too high, no side bar, no back bar, door opening is too narrow, stall is too narrow

Toilet Compartments (Stalls) – **YES except doors are not self-closing**

General Summary of the Facility

No. of Accessible Entrances: N/A

No. of Accessible Toilet Rooms: 0

No. of Accessible Drinking Fountains: N/A

No. of Accessible Floors: N/A

No. of Barriers Identified for Correction: 4

Services Provided at this Facility

Restrooms

Facility: **POINT DOUGLAS SWIM RESTROOMS**

Toilet Rooms

Accessible Route – **YES, all standards met**

Signs at Toilet Rooms – **YES except, Women’s has no braille, sign not mounted on latch side, sign too high**

Entrance – **YES except closes too quickly**

In the Toilet Room – **YES except mirrors are too high**

Lavatories – **YES except pipes are not insulated**

Soap Dispensers and Hand Dryers – **YES except soaps are too high**

Water Closets in Single-User Toilet Rooms and Compartments (Stalls) –

Women’s – YES except toilet is too high, side bar is too short and positioned incorrectly, no back bar, TP is too close to toilet

Men’s – YES except side bar is too short and positioned incorrectly, no back bar, TP is too close to toilet

Toilet Compartments (Stalls) – **YES except maneuvering clearances are too small, stalls are too narrow**

General Summary of the Facility

No. of Accessible Entrances: N/A

No. of Accessible Toilet Rooms: 0

No. of Accessible Drinking Fountains: N/A

No. of Accessible Floors: N/A

No. of Barriers Identified for Correction: 17

Services Provided at this Facility

Restrooms

Facility: Square Lake

Access to Goods and Services

Toilet Rooms

Accessible Route- **Standards met**

Signs at Toilet Rooms- **characters not raised, no braille, sign not mounted on latch side of door**

Entrance- **standards met**

In the Toilet Room- **standards met**

Lavatories- **pipes were not insulated or protected against contact**

Soap Dispensers and Hand Dryers- **standards met**

Water Closets in Single-User Toilet Rooms and Compartments (Stalls)- **m/w stalls were to narrow**

Toilet Compartments (Stalls)- **m/w grab bar does not meet standards, pulls are not on both sides of the door, m/w stalls are to narrow**

Additional Access

Drinking Fountains

Fire Alarm Systems

General Summary of the Facility

No. of Accessible Entrances: 1

No. of Accessible Toilet Rooms: 1

No. of Accessible Floors: 1

No. of Barriers Identified for Correction: 4

Services Provided at this Facility

Restrooms for swimming beach

Facility: **ST. CROIX BLUFFS CAMPGROUND RESTROOMS**

Toilet Rooms

Accessible Route – **YES, all standards met**

Signs at Toilet Rooms – **YES, all standards met**

Entrance – **YES except doors close too quickly, Men’s handle is too low**

In the Toilet Room – **YES except Men’s mirror hung too high**

Lavatories – **YES except pipes are not insulated**

Soap Dispensers and Hand Dryers – **YES, all standards met**

Water Closets in Single-User Toilet Rooms and Compartments (Stalls) – **YES, all standards met**

Toilet Compartments (Stalls) – **YES except doors are not self-closing**

General Summary of the Facility

No. of Accessible Entrances: N/A

No. of Accessible Toilet Rooms: 0

No. of Accessible Drinking Fountains: N/A

No. of Accessible Floors: N/A

No. of Barriers Identified for Correction: 4

Services Provided at this Facility

Restrooms

Facility: **St. Croix Bluffs Contact Station**

Access to Goods and Services

Interior Accessible Route – **YES, all standards met**

Signs – **YES, all standards met**

Sales and Service Counters – **YES except counter is too high**

Toilet Rooms

Accessible Route – **YES, all standards met**

Signs at Toilet Rooms – **YES, all standards met**

Entrance – **YES, all standards met**

In the Toilet Room – **YES, all standards met**

Lavatories – **YES except pipes are not insulated**

Soap Dispensers and Hand Dryers – **YES, all standards met**

Water Closets in Single-User Toilet Rooms and Compartments (Stalls) – **YES, all standards met**

Additional Access

Drinking Fountains – **YES, all standards met**

Public Telephones - **YES except operable parts are too high, bottom edge is too high and sticks too far out into path**

Fire Alarm Systems – **YES, all standards met**

General Summary of the Facility

No. of Accessible Entrances: 1

No. of Accessible Toilet Rooms: 0

No. of Accessible Drinking Fountains: 1

No. of Accessible Floors: 1

No. of Barriers Identified for Correction: 9

Services Provided at this Facility

Restrooms, Drinking fountains, Service Counter, Pay phone

Facility: **ST. CROIX BLUFFS PLAYGROUND RESTROOMS**

Toilet Rooms

Accessible Route – **YES, all standards met**

Signs at Toilet Rooms – **YES except no raised text, no braille, not mounted on latch side of door, signs hung too high**

Entrance – **YES except doors close too quickly**

In the Toilet Room – **YES except mirrors hung too high**

Lavatories – **YES except pipes are not insulated**

Soap Dispensers and Hand Dryers – **YES except soaps are hung too high,**

Water Closets in Single-User Toilet Rooms and Compartments (Stalls) –

Women’s – YES except toilet is located too far from side wall, toilet is too high, side bar is too short and positioned incorrectly, TP is too close to toilet

Men’s – YES except side bar is too short and positioned incorrectly, TP is too close to toilet

Toilet Compartments (Stalls) – **YES except doors are not self-closing**

General Summary of the Facility

No. of Accessible Entrances: N/A

No. of Accessible Toilet Rooms: 0

No. of Accessible Drinking Fountains: N/A

No. of Accessible Floors: N/A

No. of Barriers Identified for Correction: 17

Services Provided at this Facility

Restrooms